

Product Name:	HPL – 545, HPL – 577, HPL – 599	
	545 - BERGSTAK, 577 - MINITEK, 599 - MICROSPACE	
Product Manager:	Flora Chuang / Product Manager HPL 545	
Subject:	Notification of Change with Immediate Effectivity	
Distribution:	Affected customers	
Type of Change:	Materials Change	
Change Description:	Change of plastic housing colour from slight yellow to more yellowish colour due to additive changes in the pigment. 	
Reason for Change:	We have received Supplier PCN for the change of color pigment to more yellowish compared with the pale yellow colour as per picture shown above. Change is due to shortage of pigment chemicals used earlier. All the properties of resin are within the acceptable internal inspection specification.	
Affected Parts:	See Affected Parts.xls file	
Effective Date of Change:	June,25 2026	
Last Time Buy Date:	NA	
Earliest Disty Return Date:	NA	
Last Time Shipment Date	NA	
Datasheet Attached?	No	
Qual/Test Data Attached?	No	
Samples Availability Date:	25 June ,2026	
Available Alternatives?		
Questions?	Contact your local ACS Representative, or Product Manager	
	Flora Chuang / Product Manager	
	flora.chuang@amphenol-fci.com	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .