



Product Change Notification

Current Date: 03-Aug-2026

TE Connectivity

Product Change Notification: PCN-26-285489

PCN Date: 15-JUL-26

Customer: Premier Farnell UK Ltd (PFUK) (101113)

Location: Leeds

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)

SR2M / V23047 Relays - reinstated CCC certification

General Description of Changes

Dear Customer, we are pleased to inform you that the CCC certification for our SR2M / V23047 product family has been successfully reinstated. As a result, all affected SR2M part numbers listed below that are manufactured going forward will once again carry the CCC mark on the relay cover. Please note that this change may apply to a portion of the relays produced with date code 2629. However, all relays manufactured with date code 2630 and later will definitively include the CCC marking. This certification reinstatement ensures continued compliance with CCC requirements. Should you have any questions, please do not hesitate to contact your TE Connectivity representative.

Reason for Changes:

Reinstated CCC certification.

PCN Attributes:

Product Category:

Relays, Contactors & Switches

Kind of Change:

Revision Adjustment / Part Clarification

Change Feature:

Clarification/Correction

Potential Customer Impact:

Remarks:

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Ship Date of Changed Items (Changed Parts Only):

17-JUL-2026

Last Ship Date of Changed Items (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Effectivity Date:

Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO		2885651	V23047-A1021-A501, V23047A1021A501			
1-1393258-5	NO		1175064	V23047-A1024-A501, V23047A1024A501			
1-1393258-7	NO		1652616	V23047-A1024-A511,,F97243-000,AMPS-1-1393258-7, V23047A1024A511			
1393258-2	NO		2885523	V23047-A1005-A501, V23047A1005A501			
1393258-4	NO		1175062	V23047-A1012-A501, V23047A1012A501			
1393258-5	NO		2060770	V23047-A1012-A511, V23047A1012A511			
9-1415011-1	NO			V23047-A1048-A511, V23047A1048A511			