

Product Discontinuation Notice, 7/15/2026

This bulletin is being provided for informational purposes only and should never be circulated outside of Trumeter

As part of Trumeter's continuous effort to manage our product portfolio responsibly, the following 18 Series products have been reviewed and will be discontinued.

Reason for change

The production tooling used to manufacture the 18 Series has failed. Based on current and forecast sales volumes, the cost to repair or replace the tooling cannot be commercially justified.

Details of change

The following part numbers are discontinued with no further production planned:

<i>Product</i>	<i>Details of change</i>	<i>Product Transition Date</i>
E2M-1804	Product discontinued. No further production is planned.	Effective immediately
E3-1804	Product discontinued. No further production is planned.	Effective immediately

Actions required by yourself

Immediately stop quoting, accepting orders, or shipping E2M-1804 and E3-1804. Cancel all open shipments and orders.

Troy Dixon
Product Manager