Software



38SW-A Software for Multimeter 38XR-A

- Windows software for transferring and processing data to/on a PC
- Extensive export function for processing measurement data, e.g. with MS Excel*
 • RS-232 data cable included

Order No. 2727813



TM-SWA **Software for TMA10A** and TMD90A

- Windows software for transferring and processing displaying data to/on a PC
- RS-232 data cable included

Order No. 3027085



USB-KIT2 Software for ACD-45PQ and **ACD-16 TRMS-PRO**

- Windows software for transferring and processing data to/on a PC
- data cable included

Order No. 3804929



RS-232 to USB Converter Cable

Order No. 2389565



Interface adapter for TELARIS

• For connection to a PC via RS-232

Order No. 2145770



AMPRB-ET4 Earth Testing Accessory Kit

• Supported product: TELARIS EARTH

Scope of supply:

1 x Carrying case

4 x Spikes (235 x Ø 10 mm),

1 x Test lead red (25 m)

1 x Test lead blue (25 m),

1 x Test lead green (5 m) 1 x Test lead black (5 m)

4 x Cable reel

4 x Crocodile clips

Order No. 3352363