

---

# **PRODUCT ADVISORY**

## **Data Sheet Specification Change for the Listed Intersil ISL2631\* Products**

**Refer to:  
PA12059**

**Date: July 12, 2012**

July 12, 2012

To: Our Valued Intersil Customer

Subject: **Data Sheet Specification Change for the Listed Intersil ISL2631\* Products**

This advisory is to inform you that Intersil has updated the data sheet specification for the listed ISL2631\* products. The updates affect the options for configuring the voltage reference input to the device and are necessary to maintain product performance in accordance with the electrical specifications table. The option to use the *Internal 2.5V Voltage Reference* has been eliminated leaving the need for an external reference voltage to be supplied to the VREF pin. As such, all specifications and references to the operation of the Internal 2.5V Voltage Reference have been removed from the data sheet. The updated data sheet is available on the Intersil web site at <http://www.intersil.com/data/fn/fn7549.pdf>.

Products affected:

ISL26312FVZ	ISL26314FVZ	ISL26315FVZ	ISL26319FVZ
ISL26312FVZ-T	ISL26314FVZ-T	ISL26315FVZ-T	ISL26319FVZ-T
ISL26312FVZ-T7A	ISL26314FVZ-T7A	ISL26315FVZ-T7A	ISL26319FVZ-T7A

There have been no changes made to the die/silicon or device itself so there will be no impact to any existing working applications currently using this device. There will be no change in external marking of the packaged parts.

Intersil will take all necessary actions to conform to agreed upon customer requirements and to ensure the continued high quality and reliability of Intersil products being supplied. Customers may expect to continue receiving product processed to the same established conditions and systems used for manufacturing of material supplied today.

If you have concerns with this advisory, Intersil must hear from you promptly. Please contact the nearest Intersil Sales Office or call the Intersil Corporate line at 1-888-468-3774, in the United States, or 1-321-724-7143 outside of the United States.

Regards,



Jon Brewster  
Intersil Corporation

PA12059

CC: J. Touvell N. Jayaram E. Kohler