



12500 TI Boulevard, MS 8640, Dallas, Texas 75243

**PCN# 20130724002
Datasheet update for DRV632 Devices
Information Only**

Date: 8/6/2013
To: Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only. Please see the attachment details for the planned implementation date.

This notification period is per TI's standard process. Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services
Phone: +1(214) 480-6037
Fax: +1(214) 480-6659

20130724002
Attachment: 1

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
DRV632PWR	null
DRV632PW	null

Technical details of this Product Change follow on the next page(s).


PCN Number:	20130724002	PCN	08/06/2013
Title:	Datasheet update for DRV632 Devices		
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037
Change Type:	<input checked="" type="checkbox"/>	Dept:	Quality Services
	Electrical Specification		

PCN Details

Description of Change:

The product datasheet is being updated to remove min datasheet spec of 90dB for SNR and DNR. Will leave only TYP spec of 105dB. Affected devices are listed in "Product Affected" section.

The following change history provides further details. These changes may be reviewed at the datasheet link provided.

 <small>www.ti.com</small>	DRV632 <small>SLOS681A – JANUARY 2011 – REVISED JULY 2013</small>
REVISION HISTORY	
Changes from Original (January 2011) to Revision A	Page
• Deleted min value for SNR and DNR in <i>OPERATING CHARACTERISTICS</i> table	3
• Changed description of UVP in <i>PIN FUNCTIONS</i> table	4

The datasheet number will be changing.

Device Family	Change From:	Change To:
DRV632	SLOS681	SLOS681A

The updated datasheet can be accessed by the following link:

<http://www.ti.com/product/drv632>

Reason for Change:

Compliance with test program

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None

Product Affected:

DRV632PW	DRV632PWR
----------	-----------

For questions regarding this notice, e-mails

E-Mail

USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com