



Product Change Notification



Product Group: Vishay Siliconix/ May 15, 2006/**PCN-SIL-0162006 Rev 1**
August 9, 2012/**PCN-SIL-0162006 Rev 2**
November 13, 2015/**PCN-SIL-0162006 Rev 3**

Notification of Obsolescence of Vishay Siliconix HiRel / Military Product (Revision 3, Parts list amended)

DESCRIPTION OF CHANGE: Over the past decade, our Hi Rel product portfolio has seen declining demand as the parts reached the end of their lifecycle. At the same time, older wafer fabrication plants have been closed as we moved to newer facilities. As a result, we are unable to produce many die types in the Hi Rel range, and have been utilizing remaining die inventory to support this business. Recently, demand for some of these parts has increased, and we have used up this buffer inventory more rapidly than forecasted.

PCN-SIL-0162006 Rev 2 updates the obsolescence list to include parts left off revision 0 and 1.
PCN-SIL-0162006 Rev 3 Due to the closure of the Santa Clara wafer fab, additional products and technologies are added. In addition, the status of inventory has been revised

CLASSIFICATION OF CHANGE: Wafer /Chip/Pellet Site

REASON FOR CHANGE: Rev 3: Fab closure

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: NA

PRODUCT CATEGORY: Linear IC products built to HiRel/Military standards

PART NUMBERS/SERIES/FAMILIES AFFECTED: See Page 2 of this PCN

VISHAY BRAND(s): Vishay Siliconix

TIME SCHEDULE: The amended table separates parts into three categories:

Category	Inventory	Comment
1	None Remaining	Obsolete, no orders accepted
2	Limited volume	Orders accepted first come first served basis until inventory consumed
3	>5 years supply	Orders accepted until inventory consumed

SAMPLE AVAILABILITY: NA

PRODUCT IDENTIFICATION: NA

QUALIFICATION DATA: NA

ISSUED BY: Don Larson, Vishay Siliconix, Product Marketing Manager. E-mail address: don.larson@Vishay.com

For further information, please contact your regional Vishay office.

The Americas

Vishay Siliconix
2201 Laurelwood Road
Santa Clara, Ca 95054
T: 408-567-8500
F: 408-567-8942

Europe

Vishay Electronic GmbH
Dr.-Felix-Zandman-Platz 1
D-95100
Selb, Germany
T: 49-9287-71 0
F: 49-9287-70435

Asia

Vishay Intertechnology Asia Pte. Ltd
25 Tampiness Street 92
#02-00 Keppel Building
Singapore 528877
T: 65-6788-6668
F: 65-6788-0988



Product Change Notification



AMENDED PARTS LIST (PCN Revision 3)

Parts	Status	Parts	Status	Parts	Status	Parts	Status
2N4856JAN02	3	9068901EA	3	DG408AK	3	SJM201BEA01	3
2N4856JTX02	3	9073101EA	2	DG408AK-E3	3	SJM301BCA01	3
2N4856JTXV02	3	90731022A	2	DG409AK	3	SJM301BIA01	3
2N4857JAN02	3	9073102EA	2	DG409AK-E3	3	SJM301BIC01	3
2N4857JTX02	3	9073706PA	3	DG411AK-E3	2	SJM304BCA01	3
2N4858JAN02	2	9076401EA	3	DG412AK	2	SJM304BIA01	3
2N4858JTX02	2	92041012A	3	DG417AK	1	SJM306BCA01	3
2N4858JTXV02	2	9204101EA	3	DG417BAK-E3	3	SJM307BCA01	3
2N4860JTX02	3	92041022A	3	DG419AK	1	SJM307BCC01	3
2N4861JAN02	2	9204102EA	3	DG419BAK-E3	3	U290	2
2N4861JTXV02	2	92042012A	3	DG441AK	3	U291	2
2N5114JTX02	2	9204201XA	3	DG542AP	3	U291-E3	2
2N5115JAN02	3	9204201XC	3	DM1038	3	U310	2
2N5115JTX02	3	92042022A	3	DM1123	3	U310-E3	2
2N5115JTXV02	3	9204202EA	3	DM125201	3	U430	2
2N5433	3	9204202XA	3	DN1328	2	U430-E3	2
2N5433-2	3	9562302XA	1	DN2298	2	U431	2
2N5545JTX01	3	9562901CA	3	DN2307	2	U440	2
2N5546JTXL01	3	DG183AP/883	3	FN3484	2	U440-E3	2
2N6659	3	DG184AP/883	3	FN4839	2	U441-E3	2
2N6659-2	3	DG186AP/883	3	FN5519	2	V1349401	3
2N6659-E3	3	DG187AA/883	3	FN5604	2	VN10KE-2	1
2N6660	3	DG187AP/883	3	IBADADWF	3	VNDQ2DWF	3
2N6660-2	3	DG188AA	1	LSBGCDWF	3	VP0300B	3
2N6660-E3	3	DG200AAA	3	SD210DE-2	3	VP0808B	2
2N6660JTX02	3	DG200AAA/883	3	SD214DE-2	2	VP0808B-E3	2
2N6660JTXL02	3	DG200AAK	3	SD215DE-2	3	VP1008B	2
2N6660JTXV02	3	DG200ABK	3	SDG200259	3	VQ1001P	2
2N6661	3	DG201BAK	3	SDG41124	2	VQ1001P-E3	2
2N6661-2	3	DG201BDK	3	SDG61305	3	VQ1004P	3
2N6661-E3	3	DG202BAK	2	SDG8248	3	VQ1004P-E3	3
2N6661JTX02	3	DG301AAA	3	SJM181BCA01	3	VQ1006P	3
2N6661JTXL02	3	DG301AAA/883	3	SJM184BEA01	3	VQ1006P-2	3
2N6661JTXV02	3	DG301AAK	3	SJM187BCA01	3	VQ1006P-E3	3
7801401XA	3	DG301AAK/883	3	SJM187BIA01	3	VQ2001P	3
8671602EA	2	DG304AAK/883	3	SJM187BIC01	3	VQ2001P-2	3
8767301CA	3	DG307AAK/883	3	SJM190BEA01	3	VQ3001P-E3	2
8767301XA	3	DG307BDWF	1	SJM190BEC01	3		
8768901VA	2	DG387AAA/883	3	SJM200BIA01	3		
8976301EA	1	DG387AAK/883	3	SJM200BIC01	3		