



## Product/Process Change Notice - PCN 13\_0027 Rev. A

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Material Report). Any issues with this PCN or requirements to qualify the change (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

*Note: Revised fields are indicated by a red field name. See Appendix B for revision history.*

**PCN Title:** ADG5408/ADG5409 Datasheet Specification Change  
**Publication Date:** 11-Mar-2013  
**Effectivity Date:** 11-Mar-2013 *(the earliest date that a customer could expect to receive changed material)*

### Revision Description:

Correction of typographical errors in previous revision of PCN

### Description Of Change

The current carrying capability of the ADG5408 and ADG5409 TSSOP and LFCSP packages is being increased as per the attached document.

Revision A of PCN - Correction as follows:

Table 5; VDD = 36V; LFCSP package @ 85C changed from 11 to 116.

Table 6; VDD = 36V; LFCSP package @ 85C changed from 67 to 97.

### Reason For Change

The datasheet is being updated to accurately reflect the device capabilities of the ADG5408 and ADG5409

### Impact of the change (positive or negative) on fit, form, function & reliability

There is no change in product design and the specification change will not have any impact on the quality or reliability of the devices.

### Summary of Supporting Information

Changes will be reflected in Revision C of ADG5408/ADG5409 datasheet

### Supporting Documents

**Attachment 1:** Type: Detailed Change Description

ADI\_PCN\_13\_0027\_Rev\_A\_Continuous Current per Channel RevB to RevC.pdf

For questions on this PCN, send email to the regional contacts below or contact your local ADI sales representative

<b>Americas:</b>	PCN_Americas@analog.com	<b>Europe:</b>	PCN_Europe@analog.com	<b>Japan:</b>	PCN_Japan@analog.com
				<b>Rest of Asia:</b>	PCN_ROA@analog.com



**Appendix A - Affected ADI Models**

**Existing Parts - Product Family / Model Number (6)**

ADG5408 / ADG5408BCPZ-REEL7	ADG5408 / ADG5408BRUZ	ADG5408 / ADG5408BRUZ-REEL7	ADG5409 / ADG5409BCPZ-REEL7	ADG5409 / ADG5409BRUZ
ADG5409 / ADG5409BRUZ-REEL7				

**Appendix B - Revision History**

<b>Rev</b>	<b>Publish Date</b>	<b>Effectivity Date</b>	<b>Rev Description</b>
Rev. -	11-Feb-2013	11-Feb-2013	Initial Release
Rev. A	11-Mar-2013	11-Mar-2013	Correction of typographical errors in previous revision of PCN

Analog Devices, Inc.

DocId:2308 Parent DocId:None Layout Rev:7