

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN# 20150529000 Datasheet update for LMP92066 Information Only Datasheet

Date: 6/4/2015 To: Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

20150529000 Information Only Datasheet Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE LMP92066PWP CUSTOMER PART NUMBER null

Technical details of this Product Change follow on the next page(s).

PCN	Number:	20150529000			PCN Da	ite: 06/04/2015	5	
Title: Datasheet update for LMP92066								
Customer Contact: PCN Manage		PCN Manager	Dept:			Quality Services		
Change Type:								
	Assembly Site	Des				Bump Site		
	Assembly Process		a Sheet			Bump Material		
	Assembly Materia		number chang	je 🗌		Bump Process Fab Site		
\square	Mechanical Specif Packing/Shipping/		: Site : Process			Fab Materials		
	Facking/Shipping/		. FIOCESS			Fab Process		
PCN Details								
Description of Change:								
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.								
	92066 634A – MARCH 2014 – REVISED	ADRII 2015				www.ti.com		
						www.ti.com		
Changes from Original (March 2014) to Revision A Page								
 Changed header row of <i>Device Information</i> table; revised "terminal" to "pin" throughout document, changed <i>Handling Ratings</i> to <i>ESD Ratings</i> table; took out "+" from positive values; italicize section cross references; add titles for tables 3, 4, 5, and 6								
	vevice Family Cha		om:		nge To:			
LM	LMP92066 SN		AS634 S		NAS634A			
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/Imp92066								
Reason for Change:								
To more accurately reflect device characteristics.								
Ant	icipated impact o	n Fit, Form, Functi	on, Quality o	· Reliabilit	ty (posi	tive / negative):		
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative): No anticipated impact. This is a specification change announcement only. There are no changes to the actual device								
Changes to product identification resulting from this PCN:								
None.								
Product Affected:								
LMP92066PWP LMP92066PWPR								

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com