



Engineering Change Notification

Product Line:	etherCON cable carriers	Part Numbers:	NE8MC, NE8MC-B, NE8MC-1, NE8MC-1-D, NE8MC-B-1
---------------	------------------------------------	------------------	--

First date code for shipments of modified product:	H37
--	------------

Comment:	Alignment of certain RJ45 connectors improved via revision of chuck stop washer
----------	--

Mixed old/new stock acceptable?	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
---------------------------------	--	------------------------------------



To improve RJ45 connector alignment, the design of the chuck stop washer has been modified. The new chuck stop washer has two alignment noses for proper positioning on the RJ45 connector. Also, a small step has been introduced to ensure better distribution of the pushing force on the RJ45 connector. For the great majority of RJ45 connectors, this change makes no difference. However, it does make a positive difference when used with a few specific RJ45 connectors.

Customers who (a) have etherCON cable carriers manufactured prior to date code H37 and (b) need the modified chuck stop washer for use with their specific RJ45 connectors can obtain the part by contacting Neutrik USA directly.