

Customer Information Notice CN004

Dear Customer,

Subject: McMurdo shroud and cable clamp screws

Part numbers affected: MDJ9- MDJ15- MDJ25-MDJ37

In our drive to continuously improve our supply chain, maintain quality and cost we have approved the change from a black zinc plate to a clear zinc plate on the two shroud securing screws and the two cable clamp screws in our McMurdo range of connectors. The change is purely cosmetic and will not affect the performance of either in both mechanical strength and corrosion resistance.

The changes can be seen form the illustration below.



The picture on the left is the old screw and the right the new.

If you have any questions regarding the change please do not hesitate to contact us.

Signed: 

ITW Quality Manager

Date: 07/01/2016