

Global Change Notification (GCN)

Product Family	Various	10709223
		GCN Number
Series	Various	September 21, 2015
		Date Issued
Reason For Change	Change Construction Or Material	
Change Description	Molex supplier is changing material of MTP and MXC connector crimp bands to eliminate the need of claiming RoHS exemption 6(c). New aluminum crimp bands are completely lead-free and offer improved aesthetic consistency. New crimp bands were tested side by side with legacy crimp bands and were found to have equivalent performance.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception		
Assessment Of Change (How Product Will Be Qualified & Validated)	No change to fit, form or function	
Internal Molex Qualification Date (Planned Date Information Available)	September 01, 2015	
Sample Availability Date (Changed Part)	January 01, 2016	
Date of Implementation	March 22, 2016	
Method of Identifying Change	Parts made after implementation date	
Recommended Replacement Parts	Not applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com