



---

**PCN# : P67BAAB**  
**Issue Date : Jul. 28, 2016**

**Information Only Notification**

This is to inform you that a change is being made to the following products.

This is a minor change that has no impact on product quality, reliability, electrical or mechanical performance. Affected products will remain fully compliant to all published specifications. Notification is being made for informational purposes only and there is no approval required. Products incorporating this change may be shipped interchangeably with existing unchanged products on or after the issue date of this notification.

Please contact your local Customer Quality Engineer if you have any questions regarding this notification.

**Implementation of change:**

Description of Change (From) :  
Electrical Characteristics, Drain-Source Diode Characteristics (Page 2)  
Trr (Reverse Recover Time) : Max= 27ns

Description of Change (To) :  
Electrical Characteristics, Drain-Source Diode Characteristics (Page 2)  
Trr (Reverse Recover Time) : Typ= 36ns , Max= 72ns

Reason for Change:  
This is a Datasheet change only.

Correcting an error on Trr value, this has now been updated based on current Characterization and Test data.



---

**Affected Product(s):**

FDD10AN06A0		
-------------	--	--