

**User Registration**

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, “how-to” and design documents, product change notices (PCN) and other valuable content available only to registered users. <http://www.silabs.com/profile>

<b>Bulletin Date:</b> 4/1/2015		<b>Bulletin Effective Date:</b> 4/1/2015	
<b>Title:</b> EFM8UB20 Revision 1.2 Data Sheet Update			
<b>Originator:</b> Kafai Leung		<b>Phone:</b> +65 6511-7750	<b>Dept:</b> MCU Marketing
<b>Customer Contact:</b> Kathy Haggar		<b>Phone:</b> +1 512-532-5261	<b>Dept:</b> Sales
<b>Bulletin Details</b>			
<b>Description:</b> In Table 4.3, Reset and Supply Monitor, of the EFM8UB2 revision 1.2 data sheet, the Max Accuracy columns have been updated to indicate 1 ms VDD Ramp Time.			
<b>Reason:</b> Silicon Labs is issuing this change notification to the EFM8UB2 data sheet in order to correct a typographical error regarding the VDD Ramp Time listed in Table 4.3 Reset and Supply Monitor of the data sheet.			
<b>Product Identification:</b> EFM8UB20F64G-A-QFP48 EFM8UB20F64G-A-QFP32 EFM8UB20F64G-A-QFN32 EFM8UB20F32G-A-QFP48 EFM8UB20F32G-A-QFP32 EFM8UB20F32G-A-QFN32			
This change is considered a minor change which does not affect form, fit, function, quality, or reliability. The information is being provided as a customer courtesy.  Please contact your local Silicon Labs sales representative with any questions about this notification. A list of Silicon Labs sales representatives may be found at <a href="http://www.silabs.com">www.silabs.com</a>			
<b>Customer Actions Needed:</b> Review data sheet 1.2			