

# **EOL Information April 2016**

---



## **Obsolete products –RP10-A / RP10-AW / RP20-FR Series**

Dear customers,

In the most recent pricelist, the option of having no suffix for the recently introduced RP10-A, RP10-AW and RP20-FR series is given, although this option is not listed in the safety certificates.

Therefore the part numbers without a suffix are being made EOL to avoid any confusion in the future. All other part numbers with suffixes are not affected.

We apologise for any additional work this error may have caused you. If you have any further questions, please contact your local office.

Issue Date: 18 April 2016  
Last time buy date: N/A  
Last delivery date: N/A

Steve Roberts  
Technical Director  
RECOM Engineering, Gmunden, Austria

For further information, please contact our sales teams:

|                       |                           |    |  |
|-----------------------|---------------------------|----|--|
| <b>Europe:</b>        | Tel: +49 (0) 6102-88381-0 | or | <a href="mailto:info@recom-electronic.com">info@recom-electronic.com</a> |
| <b>Asia:</b>          | Tel: +65 62768795         | or | <a href="mailto:enquiry@recom-power.com">enquiry@recom-power.com</a>     |
| <b>North-America:</b> | Tel: +1 718 855 9710      | or | <a href="mailto:admin@recom-power.com">admin@recom-power.com</a>         |

ENC: EOL list

