

## 1 Products affected

Product hierarchy no. *				Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type				
02	005	016	0000001143	See list below		GSF2 Power Entry Modul	n.a.

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

List of part numbers affected				
GSF2.1010.A1	GSF2.0011.01	GSF2.1010.01	GSF2.1011.01	GSF2.1013.01
GSF2.1022.01	GSF2.2010.01	GSF2.2011.01	GSF2.2013.01	GSF2.2022.01
GSF2.2035.01				

## 2 Type of change

- Change of material

## 3 Reason of change

- Product improvement to fulfil the enhanced glow wire requirements according to the updated standard IEC 60127-6 and the standard IEC 60335-1 for appliances in unattended use.
- Recertification by VDE
- Recertification by UL

## 4 Release date

The change will be rolled-out starting ww 03/2017 and lasts approx. 6 months.

## 5 Impact of change and recommended action

Form	Yes	Change of plastic material
Fit	No	No change for dimension
Function	No	No function change
Manufacturing	No	No changes for manufacturing site
Label	No	No changes on the label
Packaging	No	No change in packaging

## 6 Reference Documents / Attachments

Kind of document	Remarks
<a href="#">Datasheet GSF2</a>	

Product Change Notification					PCN GSF2		D10-012-186
owner	creation date	release date	released by	change order no	rev	page	
hollenpe	2017-01-11	2017-01-12	hollenpe	2011858	A	1 of 1	