

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number:

0897621542

Status:

Active

Overview:

RF Cable Assemblies

Description:

2.92mm Straight Plug-to-2.92mm Straight Plug, 086SC-2401 Cable, Length 304.80mm, 50 Ohms

|               |                                      |
|---------------|--------------------------------------|
| Documents:    |                                      |
| Drawing (PDF) | RoHS Certificate of Compliance (PDF) |

|                             |                       |
|-----------------------------|-----------------------|
| General                     |                       |
| Product Family              | Cable Assemblies      |
| Series                      | 89762                 |
| Assembly Configuration      | Dual Ended Connectors |
| Connector to Connector      | 2.92mm-to-2.92mm      |
| Overview                    | RF Cable Assemblies   |
| Product Name                | 2.92mm, RF            |
| UPC                         | 887191482569          |
| Physical                    |                       |
| Cable Length                | 304.80mm (1.0')       |
| Circuits (Loaded)           | 0                     |
| Gender                      | Plug/Plug             |
| Net Weight                  | 11.030/g              |
| Packaging Type              | Bag                   |
| Single Ended                | No                    |
| Wire/Cable Type             | Temp-Flex 086SC-2401  |
| Electrical                  |                       |
| Impedance                   | 50#                   |
| Solder Process Data         |                       |
| Lead-freeProcess Capability | N/A                   |
| Material Info               |                       |
| Reference - Drawing Numbers |                       |
| Sales Drawing               | SD-89762-154          |

EU ELV

Not Relevant

EU RoHS

China RoHS

Compliant with

Exemption 6(c)

REACH SVHC

Contained Per -

ED/21/2016 (20 June

2016)

2,4-Di-tert-butyl-6-(5-

chlorobenzotriazol-2-

yl)p

Halogen-Free

Status

Low-Halogen

Need more information on product

environmental compliance?

Email [productcompliance@molex.com](mailto:productcompliance@molex.com)

Please visit the [Contact Us](#) section for any

non-product compliance questions.

China ROHS

50 Image

ELV

Not Relevant

Search Parts in this Series

89762 Series

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION