

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number: [0732510450](#)
Status: **Active**
Overview: [SMA RF Connectors](#)
Description: 50 Ohms, SMA Plug, Straight, Crimp, RG-174, RG-188, and RG-316 Cable, Brass Body, Gold Plated, with Heat Shrink Tube, Tray

Documents:

[Drawing \(PDF\)](#) [RoHS Certificate of Compliance \(PDF\)](#)

General

| | |
|-----------------|-----------------------------------|
| Product Family | RF/Coax Connectors |
| Series | 73251 |
| Overview | SMA RF Connectors |
| Product Name | SMA |
| Style | Cable |
| UPC | 800756108469 |
| Wire/Cable Type | LMR-100, RG-174, RG-188, RG-316 |

Physical

| | |
|-----------------------|----------|
| Gender | Plug |
| Keying to Mating Part | None |
| Net Weight | 3.323/g |
| Orientation | Straight |
| PCB Mounting | N/A |
| Packaging Type | Tray |
| Panel Mount | No |
| Panel Mount Method | N/A |

Electrical

| | |
|-----------|-----|
| Impedance | 50# |
|-----------|-----|


Solder Process Data

| | |
|-----------------------------|-----|
| Lead-freeProcess Capability | N/A |
|-----------------------------|-----|

Material Info

Reference - Drawing Numbers

| | |
|---------------|--------------|
| Sales Drawing | SD-73251-045 |
|---------------|--------------|



EU ELV

Not Relevant

EU RoHS

Compliant with Exemption 6(c)

REACH SVHC

Contained Per - ED/21/2016 (20 June 2016)
2,4-Di-tert-butyl-6-(5-chlorobenzotriazol-2-yl)p

Halogen-Free

Status

Low-Halogen

Need more information on product environmental compliance?

Email productcompliance@molex.com
Please visit the [Contact Us](#) section for any non-product compliance questions.

China ROHS

50 Image

ELV

Not Relevant

Search Parts in this Series

[73251](#) Series