

Product Change Notification (PCN)

PCN Number	502156	Date Issued	February 13, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Corrective Actions		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	March 20, 2017		
Sample Availability Date (Changed Part)	March 20, 2017		
Planned Implementation Date	August 15, 2017		
Method of Identifying Change	Date code	SEL	
Before Change	After Change		

 Hooks and pockets being added at the 4 corners of the SFP 2x1 Connector Assemblies will keep the EMI finger straps tight to the cage body



Overview

- Hooks and pockets being added at the 4 corners of the SFP 2x1 Connector Assemblies will keep the EMI finger straps tight to the cage body.
- Assembles win keep the two iniger staps ugn to the cage body. This will prevent spring finger damage during the insertion through the customer's bezel opening.
- Product Impact

 There will be no impact to the product form, fit or function
- Part Number Impact
 - Impacts 76044 series connectors
- PPAP and samples available upon request
- 2 Nolex Confidential Information 2 © 2016 Molex – All Rights Reserved, Unauthorized Reproduction/Distribution is Prohibite

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502156**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com