

**Product Change Notification (PCN)** 

PCN Number	501706	Date Issued	February 11, 2017
Reason for Change	Supplier Change		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Reason for Short Notice	Force Majeure		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	February 06, 2017		
Sample Availability Date (Changed Part)	February 06, 2017		
Planned Implementation Date	February 27, 2017		
Method of Identifying Change	Date code After Change		
	DIAMOND KNURL 30° SPIRAL 25 T.P.I. -046 X 45° -040 MFER		
	Change in the plating supplier for component part numbers 1302000408, 1302000414 and 1302010681		

Please see attached impacted parts list. Fit Form or Function is not affected.



**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501706**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com