

Date of issue : Nov. 16, 2016

Subject: Discontinue Notice of SSF-LXH475 Series

As part of an ongoing effort to offer the most appropriate solutions to user interface technology applications, Lumex is making the decision to discontinue the following part numbers from our current product offering:

SSF-LXH475 Series :

SSF-LXH475GD	SSF-LXH475AIID	SSF-LXH475GD	SSF-LXH475GGGX
SSF-LXH475GGI	SSF-LXH475GGXX	SSF-LXH475GGY	SSF-LXH475GGYY
SSF-LXH475GIGY	SSF-LXH475GIID	SSF-LXH475GYW	SSF-LXH475GYWXS
SSF-LXH475GYXGYGYW	SSF-LXH475IC	SSF-LXH475ID	SSF-LXH475IGGG
SSF-LXH475IGW	SSF-LXH475IGW2XIGW	SSF-LXH475IGW3X	SSF-LXH475IIAD
SSF-LXH475IIIX	SSF-LXH475IIYY	SSF-LXH475IIXG	SSF-LXH475IYGI
SSF-LXH475IYGS	SSF-LXH475LGD	SSF-LXH475LGGGX	SSF-LXH475LGGI
SSF-LXH475LGIGG	SSF-LXH475LGIYX	SSF-LXH475LGXYG	SSF-LXH475LGYGY
SSF-LXH475LID	SSF-LXH475LIIX	SSF-LXH475LSBGY	SSF-LXH475LYD
SSF-LXH475SBGY	SSF-LXH475SGC	SSF-LXH475SI2SOSUG	SSF-LXH475SID
SSF-LXH475SRC	SSF-LXH475SRD	SSF-LXH475SUG	SSF-LXH475SYC
SSF-LXH475USB	SSF-LXH4755XGYGYGYW	SSF-LXH475YD	SSF-LXH475YGW
SSF-LXH475GYW3I1D	SSF-LXH475YGWXYGWI	SSF-LXH475YYGG	SSF-LXH475AYYYD5V
SSF-LXH475GAYI	SSF-LXH475GIYX	SSF-LXH475GYGY	SSF-LXH475GYYI
SSF-LXH475IAYG	SSF-LXH475IGIG	SSF-LXH475YGW3I1D	

Discontinue above part immediately.

As there is no direct replacement for this product, please contact Lumex Technical Specialists for customer support to transition any customers you might have to a new product.

If you have any questions, feel free to contact your Lumex representative for more information.

(END of the EOL)

Best Regards,

Lumex Product Management Team