

**Product Change Notification (PCN)** 

PCN Number	502552	Date Issued March 14, 2017
Reason for Change	Change to Product	
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.	
Reason for Short Notice	Special Request	
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.	
Internal Molex Qualification Date	March 15, 2017	
Sample Availability Date (Changed Part)	March 15, 2017	
Planned Implementation Date	July 31, 2017	
Method of Identifying Change	New part number	SED

## **Before Change**



## After Change

## Overview

- For continuous improvement, Molex will be upgrading the Mat Seal within the MX150 2x6 Blade for seal tear reduction
- Product Impact

1

- Mat seal hole geometry and hole location optimization
  Seal color change from rust red to royal blue
- No change to hole diameter
  Material will remain the same inherently lubricated silicone
- Part Number Impact 33482-12xx, 33482-13xx & 33482-14xx will become obsolete, replaced by 33482-62xx, 33482-63xx & 33482-64xx respectively
- PPAP and samples available upon request

molex



**Product Change Notification (PCN)** 

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:502552**" in the e-mail Subject line for faster response.

## RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com