


Product Change Notification (PCN)

PCN Number	501794	Date Issued	March 31, 2017
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Special Request		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	November 15, 2016		
Sample Availability Date (Changed Part)	November 15, 2016		
Planned Implementation Date	April 30, 2017		
Method of Identifying Change	Lot information on label		

RELEASED

Before Change




First Mating Area will be changed.

After Change

Overview

- Add gold plating at first mating area, optimize contact wiping process.
- Product Impact
 - No impact to fit
 - Impact to appearance of terminal
- Part Number Impact
 - see attached impacted parts list
- PPAP and samples available upon request



Add Gold Plating at First Mating Area



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:501794**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com