



Product Discontinuance Notice - PDN 16_0074 Rev. A

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinue Model ADL5317ACPZ-REEL7

Publication Date: 25-Apr-2017

Last Time Buy Date: 19-Dec-2017

Last Time Ship Date: 19-Dec-2018

Revision Description:

Removing ADL5317ACPZ-REEL7 from obsolescence status. This action cancels this PDN.

Reason For Discontinuance

ADI will obsolete this model due to decreased customer demand.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

| | | |
|--|--------------------------------------|---|
| Americas: PDN_Americas@analog.com | Europe: PDN_Europe@analog.com | Japan: PDN_Japan@analog.com |
| | | Rest of Asia: PDN_ROA@analog.com |

PDN 16_0074 Discontinued Parts Material List

Removed Parts Across All Revisions of PDN 16_0074 Notices

| Model | Product Family | Replacement Part | Pin To Pin Compatible | Comments |
|-------------------|----------------|------------------|-----------------------|----------|
| ADL5317ACPZ-REEL7 | ADL5317 | None | N/A | |

Appendix A - PDN 16_0074 Revision History

| Rev | Publish Date | Rev Description |
|------------|---------------------|--|
| Rev. - | 19-Dec-2016 | Initial Release |
| Rev. A | 25-Apr-2017 | Removing ADL5317ACPZ-REEL7 from obsolescence status. This action cancels this PDN. |

Analog Devices, Inc. Proprietary Information

DocId:1146 Layout Rev:2 Parent DocId:None