

1 Products affected


Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PUG	Type			
02	007	003	0000002298	See list below	Appliance Inlet	4798

*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

List of part numbers affected			
4798.9000	4798.9100	4798.9200	

2 Type of change

The socket base has to be adapted for intended versions with IP54 protection.



3 Reason of change

The socket base has to be adapted for intended versions with IP54 protection against connector.

4 Release date

The change will be rolled-out starting ww 20/2017 (Date code 2017 or higher on label) and lasts approx. 6 months depending on the variant.

5 Impact of change and recommended action

Form	Yes	There are change in form
Fit	No	No change for dimension
Function	No	No change in function
Manufacturing	No	No change for manufacturing site
Label	No	No change on label
Packaging	No	No change in packaging

6 Reference Documents / Attachments

Kind of document	Remarks
Data Sheet 4798	

Product Change Notification					PCN 4798		D10-014-610
owner	creation date	release date	released by	change order no	rev	page	
sariogar	2017-03-27	2017-04-03	sariogar	2012500	A	1 of 1	