



Product/Process Change Notice - PCN 17_0200 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. **Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date.** ADI contact information is listed below.

PCN Title: Moisture Sensitivity Level Rating Change for Select iCoupler Products - ADM3052/ADM3053/ADM3054

Publication Date: 31-Oct-2017

Effectivity Date: 31-Oct-2017 *(the earliest date that a customer could expect to receive changed material)*

Revision Description:

Initial Release

Description Of Change

Moisture Sensitivity Level (MSL) rating is being changed from MSL1 to MSL3 in accordance with Dry Pack procedures required per J-STD-033.

Reason For Change

The MSL rating is being changed from MSL1 to MSL3 to align with other equivalent iCoupler products.

Impact of the change (positive or negative) on fit, form, function & reliability

This change does not affect fit, form, function or reliability of the products.

Summary of Supporting Information

Supporting Documents None

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas: PCN_Americas@analog.com	Europe: PCN_Europe@analog.com	Japan: PCN_Japan@analog.com
		Rest of Asia: PCN_ROA@analog.com

Appendix A - Affected ADI Models

Added Parts On This Revision - Product Family / Model Number (7)

ADM3052 / ADM3052BRWZ	ADM3052 / ADM3052BRWZ-REEL7	ADM3053 / ADM3053BRWZ	ADM3053 / ADM3053BRWZ-REEL7	ADM3054 / ADM3054BRWZ
ADM3054 / ADM3054BRWZ-RL7	ADM3054 / ADM3054WBRWZ-RL7			

Appendix B - Revision History

Rev	Publish Date	Effectivity Date	Rev Description
Rev. -	31-Oct-2017	31-Oct-2017	Initial Release

Analog Devices, Inc.

DocId:4290 Parent DocId:2638 Layout Rev:7