



Product Change Notification

Current Date: 01-Dec-2017

TE Connectivity

Product Change Notification: P-17-014809

PCN Date: 06-SEP-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMP MCP 2.8 - Application Specification 114-18148

Description of Changes
Section 4.3:D)range>2.5-4.0mm increased to 2.5-6.0mm E)added (Burr on the base of crimp acc. 114-18022) Section 5.1:PN968853, 1355880 and 968859 New crimp heights added to meet new requirements of LV 214-2 Slow Motion bending test. A)Tolerance insulation crimp width for PNs968849 and 1355876 increased to +0.2/-0.5 B)Tolerance insulation crimp width for PNs968857 and 2282364 increased to +0.4/-0.25 C)PN2289061 added; column "Insulation Range" removed Section 5.2:A)Columns "Loose Piece" and "Die For Hand Tool" removed B)Columns "Loose Piece" and "Die For Hand Tool" removed; Tolerance insulation crimp width for PNs968857 and 2282364 increased to +0.4/-0.25 C)Column "Insulation Range" removed Section 5.3:A)Columns "Loose Piece" and "Die For Hand Tool" removed B)Columns "Loose Piece" and "Die For Hand Tool" removed; Tolerance insulation crimp width for PNs 968857 and 2282364 increased to +0.4/-0.25; Stripped length for PNs1719506 and 2282365 changed to 5.0C)Column "Insulation Range" removed

Reason for Changes:
Document clarification.New terminal version added, Tolerance adaption

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	02-AUG-2017
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1355833-1	NO					
1-1355876-1	NO					
1-1355877-1	NO					
1-1355880-1	NO					
1-1719506-1	NO					
1-1719506-3	NO					
1-2236751-3	NO					
1-2236752-3	NO					
1-2282364-1	NO					
1-2282364-3	NO					
1-2282365-1	NO					
1-2289061-3	NO					
1-968849-1	NO					
1-968849-2	NO					
1-968849-3	NO					
1-968851-1	NO					
1-968851-2	NO					
1-968851-3	NO					
1-968853-1	NO					
1-968853-3	NO					
1-968855-1	NO		"8202612100"			
1-968855-2	NO					
1-968855-3	NO					
1-968855-4	NO					
1-968857-1	NO					
1-968857-2	NO					
1-968857-3	NO					
1-968857-4	NO					
1-968859-1	NO					
1-968859-3	NO					

Part Number	Part Discontinued per PCN	Customer Drawing	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968859-4	NO					
1-968880-1	NO		"1-0968880-1"			
1-968880-3	NO					
1-968882-1	NO					
1-968882-2	NO					
1-968882-3	NO					

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Document(s) Being Modified:

Documents Number	Current Revision	New Revision
114-18148	B	