INFORMATION NOTE



N° 138/17

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Robust Layout TLE8209-2SA

Infineon Technologies AG Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0 Chairman of the Supervisory Board: Dr. Eckart Sünner Management Board: Dr. Reinhard Ploss (CEO), Dominik Asam, Dr. Helmut Gassel, Jochen Hanebeck Registered Office: Neubiberg Commercial Register Amtsgericht München HRB 126492

infineon **INFORMATION NOTE** N° 138/17 Robust Layout TLE8209-2SA **Products affected:** Please refer to attached affected product list 1_cip13817 Detailed Change Information: Subject: Version bit standardization and Charge Pump performance improvement. Reason: Product Robustness / Version bit standardization Description: Old <u>New</u> Version bit 02H Version bit 01H Charge Pump Charge Pump performance improvement Product Identification: Traceability assured via lot number Impact of Change: No impact on quality and reliability. Change does not influence the integrity of the final product. ► Attachments: Affected product list 1_cip13817 Intended start of 2018-05-01

If you have any questions, please do not hesitate to contact your local Sales office.

delivery: