



Product Change Notification (PCN)


PCN Number	503317	Date Issued	April 12, 2018
Reason for Change	Drawing update Only		
Change Type Description	Drawing update Only (no impact on form, fit, function, specification, material or packaging)		
Reason for Short Notice	Special Request		
Assessment of Change	No change to parts/components FFF		
Internal Molex Qualification Date	October 04, 2017		
Sample Availability Date (Changed Part)	October 04, 2017		
Planned Implementation Date	July 11, 2018		
Method of Identifying Change	No special marking on the product or packaging		


RFI EASFD

Before Change

1.0mm pitch WTB Pico-Clasp family Crimp terminal SD-Drawing Correction of errors.

- Before**
Lance height: 0.22mm
- Au plating 501193 Series**


- Tin plating 501334 Series**


- Target Material & Drawing**


 - **Au Plating : 501193 series**
 - 5011930000 PSD 000
 - └ 5011933000
 - └ 5011933100
 - └ 5011935000
 - └ 5011935100
 - 5011930000 PSD 001
 - └ 5011932000
 - **Tin plating 501334 series**
 - SD-501334-001
 - └ 5013340000
 - └ 5013340100


After Change

Overview

- This is a PCN to correct the errors that were found in our SD for 1.0mm pitch WTB Pico-Clasp family.
- There is no change to the spec of the products and the performance that we offer to the customers.
- Process control value do not change.

- After**
Lance height: **0.28mm**
- Au plating 501193 Series**


- Tin plating 501334 Series**





Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:503317**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com