

**End Of Life Notice**  
(Notification – PLC18009)  
[30 April 2018]

**To:** Our Valued Customers

**Overview:** The purpose of this notification is to communicate that Renesas Electronics has begun the End-of-Life (EOL) Process on select part numbers.

**Affected**

**Products:** Attached is a list of products affected by this notification.

Part numbers given in the attached list are for active part numbers in the Renesas Electronics database at the time of this notification.

**Key Dates:**

Final Last Time Buy (LTB) Orders placed after this date will not be processed.	<b>31-Oct-18</b>
Last Shipment (LTS)	<b>30-April-19</b>

**Response:** Please place LTB orders in a timely manner prior to the key dates listed to avoid product availability issues. Shipments between the LTB and LTS dates are Non-Cancelable and Non-Returnable (NCNR).

Any order resulting from this notice shall be governed by Renesas's General Terms and Conditions Available at: [General Term and Conditions](#) or the applicable legal terms covering the purchase and sale transaction.

Please work with your sales representative or Field Applications Engineer to determine suitable replacement devices.

Please contact your local sales representative or Central Applications @ 1-888-468-3774 for any questions or comments.

Thank you for your attention.

Sincerely,

Renesas Electronics

Exact Intersil Part # No other variation is being impacted.	Notice PLC18009 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
5962R1121201QXC	30-Apr-18	31-Oct-18	30-Apr-19	5962R1121203VXC
5962R1121201V9A	30-Apr-18	31-Oct-18	30-Apr-19	5962R1121203V9A
5962R1121201VXC	30-Apr-18	31-Oct-18	30-Apr-19	5962R1121203VXC
5962R1121202V9A	30-Apr-18	31-Oct-18	30-Apr-19	5962R1121203V9A
5962R1121202VXC	30-Apr-18	31-Oct-18	30-Apr-19	5962R1121203VXC
5962R1121202VYC	30-Apr-18	31-Oct-18	30-Apr-19	5962R1121203VYC
5962R9572201QQC	30-Apr-18	31-Oct-18	30-Apr-19	None
5962R9572201QXC	30-Apr-18	31-Oct-18	30-Apr-19	None
5962R9572201VQC	30-Apr-18	31-Oct-18	30-Apr-19	None
5962R9572201VXC	30-Apr-18	31-Oct-18	30-Apr-19	None
CD22M3494EZ	30-Apr-18	31-Oct-18	30-Apr-19	CD22M3494MQZ
CD22M3494EZR5276	30-Apr-18	31-Oct-18	30-Apr-19	CD22M3494MQZ
CP80C88Z	30-Apr-18	31-Oct-18	30-Apr-19	CP80C88-2Z
CP82C54-12Z	30-Apr-18	31-Oct-18	30-Apr-19	CS82C54-12Z
CP82C59A-12Z	30-Apr-18	31-Oct-18	30-Apr-19	CS82C59A-12Z
CP82C84AZ	30-Apr-18	31-Oct-18	30-Apr-19	None
DG406DJZ	30-Apr-18	31-Oct-18	30-Apr-19	DG406DYZ
DG407DJZ	30-Apr-18	31-Oct-18	30-Apr-19	DG407DYZ
EL5170IYZ-T13	30-Apr-18	31-Oct-18	30-Apr-19	EL5171ISZ-T13
EL6204CWZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	EL6204CWZ-T7
GWS4621L	30-Apr-18	31-Oct-18	30-Apr-19	None
HA456CMZ	30-Apr-18	31-Oct-18	30-Apr-19	None
HD1-6408-9	30-Apr-18	31-Oct-18	30-Apr-19	None
HD3-6408-9Z	30-Apr-18	31-Oct-18	30-Apr-19	None
HD3-6409-9Z	30-Apr-18	31-Oct-18	30-Apr-19	None
HS1-80C86RH/PROTO	30-Apr-18	31-Oct-18	30-Apr-19	None
HS1-80C86RH-8	30-Apr-18	31-Oct-18	30-Apr-19	None
HS1-80C86RH-Q	30-Apr-18	31-Oct-18	30-Apr-19	None
HS9-80C86RH/PROTO	30-Apr-18	31-Oct-18	30-Apr-19	None
HS9-80C86RH-8	30-Apr-18	31-Oct-18	30-Apr-19	None
HS9-80C86RH-Q	30-Apr-18	31-Oct-18	30-Apr-19	None
ICL7107SCPLZ	30-Apr-18	31-Oct-18	30-Apr-19	ICL7107CPLZ
ISL1801IVZ	30-Apr-18	31-Oct-18	30-Apr-19	none
ISL1801IVZ-T	30-Apr-18	31-Oct-18	30-Apr-19	none
ISL23318TFRUZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZ-TK
ISL23318TFRUZ-TK	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZ-TK
ISL23318UFRUZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL23418UFUZ-TK

Exact Intersil Part # No other variation is being impacted.	Notice PLC18009 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ISL23318UFUZZ-TK	30-Apr-18	31-Oct-18	30-Apr-19	ISL23418UFUZZ-TK
ISL23318UFUZZ	30-Apr-18	31-Oct-18	30-Apr-19	ISL23418UFUZZ-TK
ISL23318UFUZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL23418UFUZZ-TK
ISL23318UFUZZ-TK	30-Apr-18	31-Oct-18	30-Apr-19	ISL23418UFUZZ-TK
ISL23418TFUZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZZ-TK
ISL23418TFUZZ-TK	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZZ-TK
ISL23418TFUZZ	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZZ-TK
ISL23418TFUZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZZ-TK
ISL23418TFUZZ-TK	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318TFUZZ-TK
ISL23418WUZZ	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318WUZZ-TK
ISL23418WUZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318WUZZ-TK
ISL23418WUZZ-TK	30-Apr-18	31-Oct-18	30-Apr-19	ISL23318WUZZ-TK
ISL29009IROZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL29009IROZZ-T7
ISL29020IROZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL29020IROZZ-T7
ISL29035IROZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL29035IROZZ-T7
ISL29101IROZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL29101IROZZ-T7
ISL29102IROZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL29102IROZZ-T7
ISL29125IROZZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL29125IROZZ-T7
ISL58792CRTZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	ISL58792CRTZ-T13
ISL6406EVAL1	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL6406EVAL2	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL6406EVAL3	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL6406IVZ	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL6406IVZ-T	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL70444SEHVFR5757	30-Apr-18	31-Oct-18	30-Apr-19	ISL70444SEHVF
ISL75051ASEHVFER5791	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVFE
ISL75051ASEHVFR5791	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVF
ISL75051SEHFE/PROTO	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHFE/PROTO
ISL75051SEHFER5760	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHFE/PROTO
ISL75051SEHVF	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVF
ISL75051SEHVFE	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVFE
ISL75051SEHVFER5760	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVFE
ISL75051SEHVFR5760	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVF
ISL75051SEHVX	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SEHVXS2745	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SEHVXS2746	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SEHVXS2747	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX

Exact Intersil Part # No other variation is being impacted.	Notice PLC18009 Issue Date	LTB / Withdrawn Date	LTS / Obsolete Date	Replacement / Similar / Re-Design
ISL75051SEHX/SAMPLE	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHX/SAMPLE
ISL75051SRHEVAL1Z	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHEV1Z
ISL75051SRHF/PROTO	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHF/PROTO
ISL75051SRHFR5760	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHF/PROTO
ISL75051SRHQF	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVF
ISL75051SRHVF	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVF
ISL75051SRHVFR5760	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVF
ISL75051SRHVX	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SRHVXS2745	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SRHVXS2746	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SRHVXS2747	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHVX
ISL75051SRHX/SAMPLE	30-Apr-18	31-Oct-18	30-Apr-19	ISL75051ASEHX/SAMPLE
ISL76120ARTZ	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL76120ARTZ-T	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL76120ARTZ-T7A	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL76120ARTZ-TR5303	30-Apr-18	30-Apr-19	31-Oct-19	None
ISL8013AIRZ-TS2568	30-Apr-18	30-Apr-19	31-Oct-19	ISL8013AIRZ-T
ISL8013IRZ-TS2568	30-Apr-18	30-Apr-19	31-Oct-19	ISL8013IRZ-T
ISL83204AIPZ	30-Apr-18	31-Oct-18	30-Apr-19	None
ISL98001CQZ-R5296	30-Apr-18	30-Apr-19	31-Oct-19	ISL98001CQZ-170, ISL98001CQZ-210, ISL98001CQZ-275
KGF12N05-400-SP	30-Apr-18	30-Apr-19	31-Oct-19	None
KGF6N05D-400	30-Apr-18	30-Apr-19	31-Oct-19	KGF16N05D-400
TIG1003IVZR5502	30-Apr-18	31-Oct-18	30-Apr-19	none
TIG1003IVZ-TR5502	30-Apr-18	31-Oct-18	30-Apr-19	none
X28HC256PIZ-90	30-Apr-18	31-Oct-18	30-Apr-19	X28HC256JIZ-90
X28HC256PZ-90	30-Apr-18	31-Oct-18	30-Apr-19	X28HC256SIZ-90 X28HC256JIZ-90
X28HC64PZ-90	30-Apr-18	31-Oct-18	30-Apr-19	X28HC64JIZ-90
X9241AUIZ	30-Apr-18	31-Oct-18	30-Apr-19	None
X9241AUPZ	30-Apr-18	31-Oct-18	30-Apr-19	None
X9241AWPIZ	30-Apr-18	31-Oct-18	30-Apr-19	None