



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000871

DATE: 19-Jul-2018

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX16930AGLS/VY+T	N/A	19-Jul-2018	19-Jul-2018	The part was not released
Discontinuance	MAX20040ATPA/V+	MAX20040ATPA/VY+	19-Jul-2018	19-Jul-2018	The part was not released
Discontinuance	MAX3110ECWI+G36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3110ECWI+TG36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3110EEWI+G36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3110EEWI+TG36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3111ECWI+G36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3111ECWI+TG36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3111EEWI+G36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3111EEWI+TG36	N/A	19-Dec-2018	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX34461ETM+	MAX34461AA00+	19-Jul-2019	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX3710EVKIT#	N/A	19-Jul-2018	19-Jul-2018	EVKIT is No Longer Supported
Discontinuance	MAX514ACWI+	N/A	19-Jul-2019	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX514AEWI+	N/A	19-Jul-2019	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX514BCWI+	N/A	19-Jul-2019	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX514BEWI+	N/A	19-Jul-2019	18-Jan-2020	Part can no longer be manufactured
Discontinuance	MAX9875EVKIT+	N/A	19-Jul-2018	19-Jul-2018	EVKIT is No Longer Supported
Discontinuance	MX7538KCWG+	N/A	19-Jul-2019	18-Jan-2020	Part can no longer be manufactured
Discontinuance	PHY1095-01DS+GR1	N/A	19-Jul-2018	19-Jul-2018	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 19-Aug-2018