




# Product Change Notification (PCN)

PCN Number	505887	Date Issued	August 10, 2018
Reason for Change	Capacity change or tool replacement		
Change Type Description	This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.		
Reason for Short Notice	New Capacity		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	December 12, 2018		
Sample Availability Date (Changed Part)	December 12, 2018		
Planned Implementation Date	December 12, 2018		
Method of Identifying Change	Product made after planned implementation date can contain the change		

RELEASED

## Before Change

- Replacement Mold
  - 1625-R1 2ckt Receptacle



## After Change

### Overview

- New Tool has been built to replace worn tooling
- Product Impact
  - No impact to fit, form or function
  - No changes are being made to the part as a result of the new tooling
- Part Number Impact
  - See attached impacted parts list.



## Product Change Notification (PCN)

---

You may address any technical inquiries regarding this PCN by sending E-mail to [pcn\\_coordinator@molex.com](mailto:pcn_coordinator@molex.com) or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505887**" in the e-mail Subject line for faster response.

RELEASED

**Molex, LLC**  
2222 Wellington Court  
Lisle, IL 60532  
TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)