

To Andrew

From time to time we find it necessary to change, modify, or replace our product offering. These changes are usually the result of advancements in technology that offer improvements in performance or manufacturability. Unavailability of component parts, generally of an earlier technology or an older design, can cause the obsolescence of outdated product families.

We sincerely appreciate your business and will make every effort to work with you during your transition to the new power supplies. In some cases of obsolescence, a new advanced model has been introduced to replace the existing power supplies. All products now being discontinued are available for an end-of-life last time buy.

We have recommended a suitable replacement for your convenience on some of the end-of-life models. If you have any questions or need specific application assistance, please contact us (you may visit <https://www.artesyn.com/contact>. Email to productsupport.ep@Artesyn.com or call 1- 888-412-7832) or your local sales representative to assist you. Thank you for your continued patronage.

The following models have been marked as EOL:

Model No	Replacement Model	Replacement Info	LTB start	LTB end
DPS52			11/30/2018	05/30/2019
DPS52-M			11/30/2018	05/30/2019
DPS53			11/30/2018	05/30/2019
DPS53-M			11/30/2018	05/30/2019
DPS54			11/30/2018	05/30/2019
DPS54-M			11/30/2018	05/30/2019
DPS55			11/30/2018	05/30/2019
DPS55-M			11/30/2018	05/30/2019
DPS58			11/30/2018	05/30/2019
DPS58-M			11/30/2018	05/30/2019
LPS52	NPS62-M	5v output 60W 2"x4" Medical and non-Medical	11/30/2018	05/30/2019
LPS52-I			11/30/2018	05/30/2019
LPS52		5v output 60W 2"x4" Medical and		