



28-Jun-2018

PCN #:E-18-009569

Subject:RYII - relays with CdO contacts. PCN P-18-015813 has already been distributed in advance. See attachment.

Description of Change: The following part numbers are being obsoleted (obsolete status). If there are suggested TE Connectivity substitute part numbers or alternate part numbers, they are shown below with any significant difference described. Please verify that all substitute or alternate part numbers provided below are suitable for your specific application- Drawings are available via TE.com.

Reason: Discontinuance. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to manage/ optimize our product portfolio throughout the lifecycle, we've made the decision to obsolete the parts stated thereafter.

Impact of Change:form - fit - function

Key Dates:

Last Order Date:31-Mar-2019

Last Ship/EOL Date:30-Sep-2019

Product Affected

7-1415507-1

(Alias Part Numbers:
"RY900114")

1-1956164-1

1-1393225-6

(Alias Part Numbers:
"RY610060")

Recommended Replacement

Product Affected**Recommended Replacement**

4-1393225-0

(Alias Part Numbers:
"RY900009")

1393225-9

(Alias Part Numbers:
"RY610009")

7-1415046-1

(Alias Part Numbers:
"RY900092")

3-1415070-1

(Alias Part Numbers:
"RY900099")

9-1393224-2

(Alias Part Numbers:
"RY550006")

6-1956150-6

1-1393225-2

(Alias Part Numbers:
"RY610018")

1-1393225-5

(Alias Part Numbers:
"RY610048")

2-1393225-2

(Alias Part Numbers:
"RY611048")

1-1393225-4

(Alias Part Numbers:
"RY610024")

2-1393225-1

(Alias Part Numbers:
"RY611024")

1-1393225-0

(Alias Part Numbers:
"RY610012")

1-1393225-9

(Alias Part Numbers:
"RY611012")

1393225-8

(Alias Part Numbers:

1-1393225-8

(Alias Part Numbers:

Product Affected	Recommended Replacement
"RY610006")	"RY611006")
1393225-7 (Alias Part Numbers: "RY610005")	1-1393225-7 (Alias Part Numbers: "RY611005")
9-1393224-6 (Alias Part Numbers: "RY550024")	1393225-2 (Alias Part Numbers: "RY551024")
9-1393224-4 (Alias Part Numbers: "RY550012")	9-1393224-9 (Alias Part Numbers: "RY551012")
7-1393224-4 (Alias Part Numbers: "RY530048")	8-1393224-3 (Alias Part Numbers: "RY531048")
7-1393224-2 (Alias Part Numbers: "475012000020" "RY530024" "CA4608-000" "AMPS-7-1393224-2")	8-1393224-2 (Alias Part Numbers: "RY531024")
7-1393224-1 (Alias Part Numbers: "RY530018")	8-1393224-1 (Alias Part Numbers: "RY531018")
6-1393224-9 (Alias Part Numbers: "RY530012")	7-1393224-9 (Alias Part Numbers: "RY531012")
6-1393224-7 (Alias Part Numbers: "RY530006")	7-1393224-7 (Alias Part Numbers: "RY531006")
6-1393224-6 (Alias Part Numbers: "RY530005")	7-1393224-6 (Alias Part Numbers: "RY531005")

Product Affected	Recommended Replacement
"CB2377-000" "AMPS-6-1393224-6"))
4-1393224-1 (Alias Part Numbers: "RY210048")	5-1393224-1 (Alias Part Numbers: "RY211048")
3-1393224-8 (Alias Part Numbers: "475012000023" "RY210024")	4-1393224-9 (Alias Part Numbers: "RY211024" "E75193-000")
3-1393224-7 (Alias Part Numbers: "RY210018")	4-1393224-7 (Alias Part Numbers: "RY211018")
3-1393224-5 (Alias Part Numbers: "RY210012")	4-1393224-6 (Alias Part Numbers: "RY211012")
3-1393224-3 (Alias Part Numbers: "RY210009")	4-1393224-5 (Alias Part Numbers: "RY211009")
3-1393224-2 (Alias Part Numbers: "RY210006")	4-1393224-3 (Alias Part Numbers: "RY211006")
3-1393224-1 (Alias Part Numbers: "RY210005")	4-1393224-2 (Alias Part Numbers: "RY211005")
2-1393224-5 (Alias Part Numbers: "RYA50024")	2-1393224-8 (Alias Part Numbers: "RYA51024")
2-1393224-4 (Alias Part Numbers: "RYA50012")	2-1393224-7 (Alias Part Numbers: "RYA51012")

Product Affected

1393224-6

(Alias Part Numbers:
"RYA30024")

1393224-5

(Alias Part Numbers:
"RYA30019")

1393224-4

(Alias Part Numbers:
"RYA30012")

1393224-2

(Alias Part Numbers:
"RYA30006")

1393224-1

(Alias Part Numbers:
"RYA30005")

Recommended Replacement

1-1393224-2

(Alias Part Numbers:
"RYA31024")

1-1393224-1

(Alias Part Numbers:
"RYA31019")

1393224-9

(Alias Part Numbers:
"RYA31012")

1393224-8

(Alias Part Numbers:
"RYA31006")

1393224-7

(Alias Part Numbers:
"RYA31005")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.