

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

Reason: End of Life

Original: PD_012_16 dated 2016-02-04

Update: **Extended LOD and LDD**

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|------------------|-------------|--------------------|---------|-------------------|-----------|------|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAL 74 E6327 | SP000014992 | BAL74E6327HTSA1 | SOT23 | | | none | |
| BAL 99 E6327 | SP000010159 | BAL99E6327HTSA1 | SOT23 | | | none | |
| BAR 74 E6327 | SP000010202 | BAR74E6327HTSA1 | SOT23 | | | none | |
| BAS 116 E6327 | SP000010194 | BAS116E6327HTSA1 | SOT23 | | | none | |
| BAS 16 E6327 | SP000010203 | BAS16E6327HTSA1 | SOT23 | | | none | |
| BAS 16 E6393 | SP000010204 | BAS16E6393HTSA1 | SOT23 | | | none | |
| BAS 16 E6433 | SP000010201 | BAS16E6433HTMA1 | SOT23 | | | none | |
| BAS 16-02L E6327 | SP000013548 | BAS1602LE6327XTMA1 | TSLP-2 | | | none | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|------------------|-------------|--------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAS 16-02V H6327 | SP000752008 | BAS1602VH6327XTSA1 | SC79 | | | | none |
| BAS 16-03W E6327 | SP000010213 | BAS1603WE6327HTSA1 | SOD323 | | | | none |
| BAS 16S H6327 | SP000753162 | BAS16SH6327XTSA1 | SOT363 | | | | none |
| BAS 16U E6327 | SP000012608 | BAS16UE6327HTSA1 | SC74 | | | | none |
| BAS 16U E6727 | SP000012609 | BAS16UE6727HTSA1 | SC74 | | | | none |
| BAS 16W H6327 | SP000753166 | BAS16WH6327XTSA1 | SOT323 | | | | none |
| BAS 21 E6327 | SP000010217 | BAS21E6327HTSA1 | SOT23 | | | | none |
| BAS 21 E6359 | SP000010222 | BAS21E6359HTMA1 | SOT23 | | | | none |
| BAS 21 E6433 | SP000010219 | BAS21E6433HTMA1 | SOT23 | | | | none |
| BAS 21-03W E6327 | SP000012522 | BAS2103WE6327HTSA1 | SOD323 | | | | none |
| BAS 21-03W E6433 | SP000082470 | BAS2103WE6433HTMA1 | SOD323 | | | | none |
| BAS 21U E6327 | SP000012610 | BAS21UE6327HTSA1 | SC74 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAS 21U E6359 | SP000012611 | BAS21UE6359HTMA1 | SC74 | | | | none |
| BAS 21U E6433 | SP000471142 | BAS21UE6433HTMA1 | SC74 | | | | none |
| BAS 28 E6327 | SP000010225 | BAS28E6327HTSA1 | SOT143 | | | | none |
| BAS 28 E6359 | SP000010229 | BAS28E6359HTMA1 | SOT143 | | | | none |
| BAS 28 E6433 | SP000010228 | BAS28E6433HTMA1 | SOT143 | | | | none |
| BAV 170 E6327 | SP000010325 | BAV170E6327HTSA1 | SOT23 | | | | none |
| BAV 170 E6359 | SP000010329 | BAV170E6359HTMA1 | SOT23 | | | | none |
| BAV 170 E6433 | SP000010332 | BAV170E6433HTMA1 | SOT23 | | | | none |
| BAV 199 E6327 | SP000010326 | BAV199E6327HTSA1 | SOT23 | | | | none |
| BAV 199 E6359 | SP000010328 | BAV199E6359HTMA1 | SOT23 | | | | none |
| BAV 199 E6433 | SP000010330 | BAV199E6433HTMA1 | SOT23 | | | | none |
| BAV 70 E6327 | SP000014923 | BAV70E6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAV 70 E6433 | SP000014924 | BAV70E6433HTMA1 | SOT23 | | | | none |
| BAV 70S H6327 | SP000753172 | BAV70SH6327XTSA1 | SOT363 | | | | none |
| BAV 70S H6727 | SP000753176 | BAV70SH6727XTSA1 | SOT363 | | | | none |
| BAV 70U E6327 | SP000012931 | BAV70UE6327HTSA1 | SC74 | | | | none |
| BAV 70U E6359 | SP000012932 | BAV70UE6359HTMA1 | SC74 | | | | none |
| BAV 70W H6327 | SP000754042 | BAV70WH6327XTSA1 | SOT323 | | | | none |
| BAV 70W H6433 | SP000754044 | BAV70WH6433XTMA1 | SOT323 | | | | none |
| BAV 99S H6327 | SP000754046 | BAV99SH6327XTSA1 | SOT363 | | | | none |
| BAV 99U E6359 | SP000012614 | BAV99UE6359HTMA1 | SC74 | | | | none |
| BAW 101 E6327 | SP000010363 | BAW101E6327HTSA1 | SOT143 | | | | none |
| BAW 156 E6327 | SP000010327 | BAW156E6327HTSA1 | SOT23 | | | | none |
| BAW 56S H6327 | SP000754060 | BAW56SH6327XTSA1 | SOT363 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-------------------|-------------|---------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAW 56S H6727 | SP000754064 | BAW56SH6727XTSA1 | SOT363 | | | | none |
| BAW 56U E6327 | SP000014993 | BAW56UE6327HTSA1 | SC74 | | | | none |
| BC 807U E6327 | SP000012395 | BC807UE6327HTSA1 | SC74 | | | | none |
| BC 817K-16 E6327 | SP000271788 | BC817K16E6327HTSA1 | SOT23 | | | | none |
| BC 817K-16 E6433 | SP000271829 | BC817K16E6433HTMA1 | SOT23 | | | | none |
| BC 817K-25 E6327 | SP000271875 | BC817K25E6327HTSA1 | SOT23 | | | | none |
| BC 817K-25 E6433 | SP000271879 | BC817K25E6433HTMA1 | SOT23 | | | | none |
| BC 817K-25W H6327 | SP000746848 | BC817K25WH6327XTSA1 | SOT323 | | | | none |
| BC 817SU E6327 | SP000296413 | BC817SUE6327HTSA1 | SC74 | | | | none |
| BC 817U E6327 | SP000012394 | BC817UE6327HTSA1 | SC74 | | | | none |
| BC 817UPN E6327 | SP000012398 | BC817UPNE6327HTSA1 | SC74 | | | | none |
| BC 846U E6327 | SP000012619 | BC846UE6327HTSA1 | SC74 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-------------------|-------------|----------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BC 856U E6327 | SP000012620 | BC856UE6327HTSA1 | SC74 | | | | none |
| BCR 523U E6327 | SP000013381 | BCR523UE6327HTSA1 | SC74 | | | | none |
| SMBTA 06UPN E6327 | SP000012393 | SMBTA06UPNE6327HTSA1 | SC74 | | | | none |
| BCV 61B E6327 | SP000010886 | BCV61BE6327HTSA1 | SOT143 | | | | none |
| BCV 61B E6433 | SP000010888 | BCV61BE6433HTMA1 | SOT143 | | | | none |
| BCV 61C E6327 | SP000010887 | BCV61CE6327HTSA1 | SOT143 | | | | none |
| BCV 62A E6327 | SP000010889 | BCV62AE6327HTSA1 | SOT143 | | | | none |
| BCV 62B E6327 | SP000010890 | BCV62BE6327HTSA1 | SOT143 | | | | none |
| BCV 62B E6433 | SP000010893 | BCV62BE6433HTMA1 | SSOT143 | | | | none |
| BCV 62C E6327 | SP000010891 | BCV62CE6327HTSA1 | SOT143 | | | | none |
| BGX 50A E6327 | SP000011092 | BGX50AE6327HTSA1 | SSOT143 | | | | none |
| BCP 52-16 H6327 | SP000748096 | BCP5216H6327XTSA1 | SOT223 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|------------------|-------------|--------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCP 53-16 H6327 | SP000748124 | BCP5316H6327XTSA1 | SOT223 | | | | none |
| BCP 54 H6327 | SP000748128 | BCP54H6327XTSA1 | SOT223 | | | | none |
| BCP 55-16 H6327 | SP000748364 | BCP5516H6327XTSA1 | SOT223 | | | | none |
| BCP 56-16 H6327 | SP000748370 | BCP5616H6327XTSA1 | SOT223 | | | | none |
| BDP 947 H6327 | SP000748376 | BDP947H6327XTSA1 | SOT223 | | | | none |
| BDP 948 H6327 | SP000748378 | BDP948H6327XTSA1 | SOT223 | | | | none |
| BC 817K-40 E6327 | SP000271895 | BC817K40E6327HTSA1 | SOT23 | | | | none |
| BC 817K-40 E6359 | SP000271897 | BC817K40E6359HTMA1 | SOT23 | | | | none |
| BC 817K-40 E6433 | SP000271898 | BC817K40E6433HTMA1 | SOT23 | | | | none |
| BC 847A E6327 | SP000010571 | BC847AE6327HTSA1 | SOT23 | | | | none |
| BC 847B E6327 | SP000010559 | BC847BE6327HTSA1 | SOT23 | | | | none |
| BC 847B E6433 | SP000010576 | BC847BE6433HTMA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BC 847C E6327 | SP000010565 | BC847CE6327HTSA1 | SOT23 | | | | none |
| BC 847C E6433 | SP000010590 | BC847CE6433HTMA1 | SOT23 | | | | none |
| BC 848A E6327 | SP000010568 | BC848AE6327HTSA1 | SOT23 | | | | none |
| BC 848B E6327 | SP000010561 | BC848BE6327HTSA1 | SOT23 | | | | none |
| BC 848C E6327 | SP000010552 | BC848CE6327HTSA1 | SOT23 | | | | none |
| BC 848C E6433 | SP000010582 | BC848CE6433HTMA1 | SOT23 | | | | none |
| BC 849B E6327 | SP000010567 | BC849BE6327HTSA1 | SOT23 | | | | none |
| BC 849C E6327 | SP000010564 | BC849CE6327HTSA1 | SOT23 | | | | none |
| BC 850C E6327 | SP000010563 | BC850CE6327HTSA1 | SOT23 | | | | none |
| BC 850C E6359 | SP000010544 | BC850CE6359HTMA1 | SOT23 | | | | none |
| BC 857A E6327 | SP000010639 | BC857AE6327HTSA1 | SOT23 | | | | none |
| BC 857B E6327 | SP000010633 | BC857BE6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BC 857B E6433 | SP000010648 | BC857BE6433HTMA1 | SOT23 | | | | none |
| BC 857C E6327 | SP000010640 | BC857CE6327HTSA1 | SOT23 | | | | none |
| BC 858A E6327 | SP000010636 | BC858AE6327HTSA1 | SOT23 | | | | none |
| BC 858B E6327 | SP000010634 | BC858BE6327HTSA1 | SOT23 | | | | none |
| BC 860B E6327 | SP000010642 | BC860BE6327HTSA1 | SOT23 | | | | none |
| BC 860C E6359 | SP000010620 | BC860CE6359HTMA1 | SOT23 | | | | none |
| BCR 108 E6327 | SP000010736 | BCR108E6327HTSA1 | SOT23 | | | | none |
| BCR 108 E6433 | SP000010737 | BCR108E6433HTMA1 | SOT23 | | | | none |
| BCR 112 E6327 | SP000010747 | BCR112E6327HTSA1 | SOT23 | | | | none |
| BCR 116 E6327 | SP000010749 | BCR116E6327HTSA1 | SOT23 | | | | none |
| BCR 116 E6433 | SP000010751 | BCR116E6433HTMA1 | SOT23 | | | | none |
| BCR 119 E6327 | SP000010752 | BCR119E6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 129 E6327 | SP000012520 | BCR129E6327HTSA1 | SOT23 | | | | none |
| BCR 133 E6327 | SP000010757 | BCR133E6327HTSA1 | SOT23 | | | | none |
| BCR 133 E6393 | SP000010758 | BCR133E6393HTSA1 | SOT23 | | | | none |
| BCR 133 E6433 | SP000010759 | BCR133E6433HTMA1 | SOT23 | | | | none |
| BCR 135 E6327 | SP000010765 | BCR135E6327HTSA1 | SOT23 | | | | none |
| BCR 135 E6359 | SP000010766 | BCR135E6359HTMA1 | SOT23 | | | | none |
| BCR 135 E6433 | SP000010767 | BCR135E6433HTMA1 | SOT23 | | | | none |
| BCR 141 E6327 | SP000010769 | BCR141E6327HTSA1 | SOT23 | | | | none |
| BCR 142 E6327 | SP000010775 | BCR142E6327HTSA1 | SOT23 | | | | none |
| BCR 146 E6327 | SP000010777 | BCR146E6327HTSA1 | SOT23 | | | | none |
| BCR 148 E6327 | SP000010780 | BCR148E6327HTSA1 | SOT23 | | | | none |
| BCR 148 E6433 | SP000426390 | BCR148E6433HTMA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 158 E6327 | SP000010784 | BCR158E6327HTSA1 | SOT23 | none | | | |
| BCR 162 E6327 | SP000010785 | BCR162E6327HTSA1 | SOT23 | none | | | |
| BCR 166 E6327 | SP000010788 | BCR166E6327HTSA1 | SOT23 | none | | | |
| BCR 166 E6433 | SP000010791 | BCR166E6433HTMA1 | SOT23 | none | | | |
| BCR 183 E6327 | SP000010794 | BCR183E6327HTSA1 | SOT23 | none | | | |
| BCR 183 E6433 | SP000010796 | BCR183E6433HTMA1 | SOT23 | none | | | |
| BCR 185 E6327 | SP000010806 | BCR185E6327HTSA1 | SOT23 | none | | | |
| BCR 191 E6327 | SP000010810 | BCR191E6327HTSA1 | SOT23 | none | | | |
| BCR 192 E6327 | SP000010812 | BCR192E6327HTSA1 | SOT23 | none | | | |
| BCR 196 E6327 | SP000014762 | BCR196E6327HTSA1 | SOT23 | none | | | |
| BCR 198 E6327 | SP000010817 | BCR198E6327HTSA1 | SOT23 | none | | | |
| BCR 503 E6327 | SP000010839 | BCR503E6327HTSA1 | SOT23 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 503 E6393 | SP000010840 | BCR503E6393HTSA1 | SOT23 | | | | none |
| BCR 505 E6327 | SP000010841 | BCR505E6327HTSA1 | SOT23 | | | | none |
| BCR 512 E6327 | SP000010844 | BCR512E6327HTSA1 | SOT23 | | | | none |
| BCR 521 E6327 | SP000010845 | BCR521E6327HTSA1 | SOT23 | | | | none |
| BCR 523 E6327 | SP000010851 | BCR523E6327HTSA1 | SOT23 | | | | none |
| BCR 523 E6433 | SP000010852 | BCR523E6433HTMA1 | SOT23 | | | | none |
| BCR 533 E6327 | SP000010853 | BCR533E6327HTSA1 | SOT23 | | | | none |
| BCR 553 E6327 | SP000010854 | BCR553E6327HTSA1 | SOT23 | | | | none |
| BCR 555 E6327 | SP000010855 | BCR555E6327HTSA1 | SOT23 | | | | none |
| BCR 555 E6433 | SP000010857 | BCR555E6433HTMA1 | SOT23 | | | | none |
| BCR 562 E6327 | SP000010859 | BCR562E6327HTSA1 | SOT23 | | | | none |
| BCR 573 E6327 | SP000010861 | BCR573E6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 573 E6433 | SP000010860 | BCR573E6433HTMA1 | SOT23 | | | | none |
| BCR 583 E6327 | SP000012278 | BCR583E6327HTSA1 | SOT23 | | | | none |
| BCV 26 E6327 | SP000010874 | BCV26E6327HTSA1 | SOT23 | | | | none |
| BCV 27 E6327 | SP000010865 | BCV27E6327HTSA1 | SOT23 | | | | none |
| BCV 27 E6395 | SP000010867 | BCV27E6395HTMA1 | SOT23 | | | | none |
| BCV 46 E6327 | SP000010873 | BCV46E6327HTSA1 | SOT23 | | | | none |
| BCV 47 E6327 | SP000010866 | BCV47E6327HTSA1 | SOT23 | | | | none |
| BCV 47 E6433 | SP000010864 | BCV47E6433HTMA1 | SOT23 | | | | none |
| BCW 60 E6422 | SP000010528 | BCW60E6422HTMA1 | SOT23 | | | | none |
| BCW 60C E6327 | SP000010548 | BCW60CE6327HTSA1 | SOT23 | | | | none |
| BCW 61 E6384 | SP000010635 | BCW61E6384HTMA1 | SOT23 | | | | none |
| BCW 61C E6327 | SP000010622 | BCW61CE6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCW 66K E6359 | SP000271901 | BCW66KE6359HTMA1 | SOT23 | none | | | |
| BCW 66KF E6327 | SP000271902 | BCW66KFE6327HTSA1 | SOT23 | none | | | |
| BCW 66KG E6327 | SP000271904 | BCW66KGE6327HTSA1 | SOT23 | none | | | |
| BCW 66KH E6327 | SP000271906 | BCW66KHE6327HTSA1 | SOT23 | none | | | |
| BCW 67B E6327 | SP000015035 | BCW67BE6327HTSA1 | SOT23 | none | | | |
| BCW 67C E6327 | SP000015037 | BCW67CE6327HTSA1 | SOT23 | none | | | |
| BCW 68 E6359 | SP000015038 | BCW68E6359HTMA1 | SOT23 | none | | | |
| BCW 68F E6327 | SP000015041 | BCW68FE6327HTSA1 | SOT23 | none | | | |
| BCW 68G E6327 | SP000015039 | BCW68GE6327HTSA1 | SOT23 | none | | | |
| BCW 68H E6327 | SP000015040 | BCW68HE6327HTSA1 | SOT23 | none | | | |
| BCX 41 E6327 | SP000010894 | BCX41E6327HTSA1 | SOT23 | none | | | |
| BCX 41 E6433 | SP000010896 | BCX41E6433HTMA1 | SOT23 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCX 42 E6327 | SP000010900 | BCX42E6327HTSA1 | SOT23 | | | | none |
| BCX 42 E6433 | SP000010902 | BCX42E6433HTMA1 | SOT23 | | | | none |
| BCX 70G E6327 | SP000010555 | BCX70GE6327HTSA1 | SOT23 | | | | none |
| BCX 70J E6327 | SP000010556 | BCX70JE6327HTSA1 | SOT23 | | | | none |
| BCX 70J E6433 | SP000010573 | BCX70JE6433HTMA1 | SOT23 | | | | none |
| BCX 70K E6327 | SP000010558 | BCX70KE6327HTSA1 | SOT23 | | | | none |
| BCX 71G E6327 | SP000010623 | BCX71GE6327HTSA1 | SOT23 | | | | none |
| BCX 71J E6327 | SP000010625 | BCX71JE6327HTSA1 | SOT23 | | | | none |
| BCX 71J E6433 | SP000010647 | BCX71JE6433HTMA1 | SOT23 | | | | none |
| BCX 71K E6327 | SP000010632 | BCX71KE6327HTSA1 | SOT23 | | | | none |
| BFN 24 E6327 | SP000014784 | BFN24E6327HTSA1 | SOT23 | | | | none |
| BFN 26 E6327 | SP000014785 | BFN26E6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|------------------|-------------|---------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BFN 27 E6327 | SP000014782 | BFN27E6327HTSA1 | SOT23 | | | | none |
| MMBT 2907A LT1 | SP000011179 | MMBT2907ALT1HTSA1 | SOT23 | | | | none |
| MMBT 3904 LT1 | SP000011671 | MMBT3904LT1HTSA1 | SOT23 | | | | none |
| MMBT 3906 LT1 | SP000011678 | MMBT3906LT1HTSA1 | SOT23 | | | | none |
| MMBTA 06 LT1 | SP000011685 | MMBTA06LT1HTSA1 | SOT23 | | | | none |
| MMBTA 56 LT1 | SP000011691 | MMBTA56LT1HTSA1 | SOT23 | | | | none |
| SMBD 7000 E6327 | SP000014938 | SMBD7000E6327HTSA1 | SOT23 | | | | none |
| SMBD 914 E6327 | SP000010209 | SMBD914E6327HTSA1 | SOT23 | | | | none |
| SMBT 2222A E6327 | SP000011176 | SMBT2222AE6327HTSA1 | SOT23 | | | | none |
| SMBT 2907A E6327 | SP000011181 | SMBT2907AE6327HTSA1 | SOT23 | | | | none |
| SMBT 3904 E6327 | SP000011673 | SMBT3904E6327HTSA1 | SOT23 | | | | none |
| SMBT 3906 E6327 | SP000011680 | SMBT3906E6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-------------------|-------------|---------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| SMBTA 06 E6327 | SP000011686 | SMBTA06E6327HTSA1 | SOT23 | none | | | |
| SMBTA 42 E6327 | SP000011000 | SMBTA42E6327HTSA1 | SOT23 | none | | | |
| SMBTA 56 E6327 | SP000011692 | SMBTA56E6327HTSA1 | SOT23 | none | | | |
| SMBTA 56 E6433 | SP000011695 | SMBTA56E6433HTMA1 | SOT23 | none | | | |
| SMBTA 92 E6327 | SP000011004 | SMBTA92E6327HTSA1 | SOT23 | none | | | |
| BC 817K-40W H6327 | SP000746850 | BC817K40WH6327XTSA1 | SOT323 | none | | | |
| BC 847BW H6327 | SP000746930 | BC847BWH6327XTSA1 | SOT323 | none | | | |
| BC 847BW H6433 | SP000746932 | BC847BWH6433XTMA1 | SOT323 | none | | | |
| BC 847CW H6327 | SP000746934 | BC847CWH6327XTSA1 | SOT323 | none | | | |
| BC 847CW H6433 | SP000747284 | BC847CWH6433XTMA1 | SOT323 | none | | | |
| BC 848BW H6327 | SP000747410 | BC848BWH6327XTSA1 | SOT323 | none | | | |
| BC 848CW H6327 | SP000747412 | BC848CWH6327XTSA1 | SOT323 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BC 850BW H6327 | SP000747416 | BC850BWH6327XTSA1 | SOT323 | | | | none |
| BC 857BW H6327 | SP000747448 | BC857BWH6327XTSA1 | SOT323 | | | | none |
| BC 857CW H6327 | SP000747452 | BC857CWH6327XTSA1 | SOT323 | | | | none |
| BC 857CW H6433 | SP000747454 | BC857CWH6433XTMA1 | SOT323 | | | | none |
| BCR 108W H6327 | SP000750780 | BCR108WH6327XTSA1 | SOT323 | | | | none |
| BCR 108W H6433 | SP000757882 | BCR108WH6433XTMA1 | SOT323 | | | | none |
| BCR 112W H6327 | SP000750790 | BCR112WH6327XTSA1 | SOT323 | | | | none |
| BCR 116W H6327 | SP000754072 | BCR116WH6327XTSA1 | SOT323 | | | | none |
| BCR 133W H6327 | SP000756246 | BCR133WH6327XTSA1 | SOT323 | | | | none |
| BCR 135W H6327 | SP000756252 | BCR135WH6327XTSA1 | SOT323 | | | | none |
| BCR 141W H6327 | SP000756258 | BCR141WH6327XTSA1 | SOT323 | | | | none |
| BCR 148W H6327 | SP000756268 | BCR148WH6327XTSA1 | SOT323 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 166W H6327 | SP000750764 | BCR166WH6327XTSA1 | SOT323 | | | | none |
| BCR 169W H6327 | SP000756844 | BCR169WH6327XTSA1 | SOT323 | | | | none |
| BCR 183W H6327 | SP000757002 | BCR183WH6327XTSA1 | SOT323 | | | | none |
| BCR 185W H6327 | SP000757894 | BCR185WH6327XTSA1 | SOT323 | | | | none |
| BCR 191W H6327 | SP000757896 | BCR191WH6327XTSA1 | SOT323 | | | | none |
| BCR 192W H6327 | SP000757898 | BCR192WH6327XTSA1 | SOT323 | | | | none |
| BCR 198W H6327 | SP000757912 | BCR198WH6327XTSA1 | SOT323 | | | | none |
| BC 846PN H6327 | SP000746856 | BC846PNH6327XTSA1 | SOT363 | | | | none |
| BC 846S H6327 | SP000746922 | BC846SH6327XTSA1 | SOT363 | | | | none |
| BC 846S H6433 | SP000746926 | BC846SH6433XTMA1 | SOT363 | | | | none |
| BC 847PN H6327 | SP000747288 | BC847PNH6327XTSA1 | SOT363 | | | | none |
| BC 847PN H6433 | SP000747292 | BC847PNH6433XTMA1 | SOT363 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BC 847PN H6727 | SP000747296 | BC847PNH6727XTSA1 | SOT363 | | | | none |
| BC 847S H6327 | SP000747298 | BC847SH6327XTSA1 | SOT363 | | | | none |
| BC 847S H6359 | SP000747402 | BC847SH6359XTMA1 | SOT363 | | | | none |
| BC 847S H6433 | SP000747404 | BC847SH6433XTMA1 | SOT363 | | | | none |
| BC 847S H6727 | SP000747406 | BC847SH6727XTSA1 | SOT363 | | | | none |
| BC 856S H6327 | SP000747446 | BC856SH6327XTSA1 | SOT363 | | | | none |
| BC 857S H6327 | SP000747456 | BC857SH6327XTSA1 | SOT363 | | | | none |
| BC 857S H6433 | SP000747576 | BC857SH6433XTMA1 | SOT363 | | | | none |
| BCM 856S H6327 | SP000747592 | BCM856SH6327XTSA1 | SOT363 | | | | none |
| BCM 856S H6433 | SP000747594 | BCM856SH6433XTMA1 | SOT363 | | | | none |
| BCR 08PN H6327 | SP000750766 | BCR08PNH6327XTSA1 | SOT363 | | | | none |
| BCR 08PN H6433 | SP000750770 | BCR08PNH6433XTMA1 | SOT363 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 08PN H6727 | SP000750772 | BCR08PNH6727XTSA1 | SOT363 | | | | none |
| BCR 108S H6327 | SP000750774 | BCR108SH6327XTSA1 | SOT363 | | | | none |
| BCR 10PN H6327 | SP000750782 | BCR10PNH6327XTSA1 | SOT363 | | | | none |
| BCR 10PN H6727 | SP000750786 | BCR10PNH6727XTSA1 | SOT363 | | | | none |
| BCR 116S H6327 | SP000752050 | BCR116SH6327XTSA1 | SOT363 | | | | none |
| BCR 119S H6327 | SP000754074 | BCR119SH6327XTSA1 | SOT363 | | | | none |
| BCR 129S H6327 | SP000755046 | BCR129SH6327XTSA1 | SOT363 | | | | none |
| BCR 133S H6327 | SP000755050 | BCR133SH6327XTSA1 | SOT363 | | | | none |
| BCR 133S H6433 | SP000755082 | BCR133SH6433XTMA1 | SOT363 | | | | none |
| BCR 135S H6327 | SP000756248 | BCR135SH6327XTSA1 | SOT363 | | | | none |
| BCR 141S H6327 | SP000756256 | BCR141SH6327XTSA1 | SOT363 | | | | none |
| BCR 148S H6327 | SP000756262 | BCR148SH6327XTSA1 | SOT363 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 148S H6433 | SP000756264 | BCR148SH6433XTMA1 | SOT363 | | | | none |
| BCR 169S H6327 | SP000756842 | BCR169SH6327XTSA1 | SOT363 | | | | none |
| BCR 183S H6327 | SP000756882 | BCR183SH6327XTSA1 | SOT363 | | | | none |
| BCR 183S H6433 | SP000756886 | BCR183SH6433XTMA1 | SOT363 | | | | none |
| BCR 185S H6327 | SP000757888 | BCR185SH6327XTSA1 | SOT363 | | | | none |
| BCR 198S H6327 | SP000757904 | BCR198SH6327XTSA1 | SOT363 | | | | none |
| BCR 22PN H6327 | SP000757916 | BCR22PNH6327XTSA1 | SOT363 | | | | none |
| BCR 22PN H6433 | SP000757920 | BCR22PNH6433XTMA1 | SOT363 | | | | none |
| BCR 35PN H6327 | SP000757922 | BCR35PNH6327XTSA1 | SOT363 | | | | none |
| BCR 35PN H6433 | SP000757928 | BCR35PNH6433XTMA1 | SOT363 | | | | none |
| BCR 48PN H6327 | SP000757930 | BCR48PNH6327XTSA1 | SOT363 | | | | none |
| BCR 48PN H6433 | SP000757932 | BCR48PNH6433XTMA1 | SOT363 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-----------------------|-------------|------------------------|----------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCV 48 H6327 | SP001125544 | BCV48H6327XTSA1 | SOT89 | none | | | |
| BCX 52 H6327 | SP001125340 | BCX52H6327XTSA1 | SOT89 | none | | | |
| BCX 55 H6327 | SP001125470 | BCX55H6327XTSA1 | SOT89 | none | | | |
| BCX 55-16 H6327 | SP001125472 | BCX5516H6327XTSA1 | SOT89 | none | | | |
| BCX 56 H6327 | SP001125476 | BCX56H6327XTSA1 | SOT89 | none | | | |
| BCX 68-25 H6327 | SP001125490 | BCX6825H6327XTSA1 | SOT89 | none | | | |
| BCX 69-16 H6327 | SP001125264 | BCX6916H6327XTSA1 | SOT89 | none | | | |
| BC 847BL3 E6327 | SP000013553 | BC847BL3E6327XTMA1 | TSLP-3 | none | | | |
| BC 857BL3 E6327 | SP000013556 | BC857BL3E6327XTMA1 | TSLP-3 | none | | | |
| CHIP T0110L-3 E6762 S | SP001155730 | CHIPT0110L3E6762SX2XA1 | bare die | none | | | |
| CHIP T0204GU E6327 | SP000414074 | CHIPT0204GUE6327X6SA1 | bare die | none | | | |
| BAV 99U E6327 | SP000012613 | BAV99UE6327HTSA1 | SC74 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|--------------------|-------------|-----------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAW 56U E6433 | SP000492394 | BAW56UE6433HTMA1 | SC74 | | | | none |
| BC 846U E6727 | SP000012618 | BC846UE6727HTSA1 | SC74 | | | | none |
| BC 846UPN E6327 | SP000012621 | BC846UPNE6327HTSA1 | SC74 | | | | none |
| BCR 183U E6327 | SP000012552 | BCR183UE6327HTSA1 | SC74 | | | | none |
| BCR 523U E6433 | SP000662374 | BCR523UE6433HTMA1 | SC74 | | | | none |
| SMBT 3904UPN E6327 | SP000012617 | SMBT3904UPNE6327HTSA1 | SC74 | | | | none |
| SMBT 3906U E6327 | SP000012616 | SMBT3906UE6327HTSA1 | SC74 | | | | none |
| BCP 49 H6327 | SP000747598 | BCP49H6327XTSA1 | SOT223 | | | | none |
| BCP 49 H6359 | SP000748082 | BCP49H6359XTMA1 | SOT223 | | | | none |
| BCP 49 H6419 | SP000748086 | BCP49H6419XTMA1 | SOT223 | | | | none |
| BCP 51 H6327 | SP000748088 | BCP51H6327XTSA1 | SOT223 | | | | none |
| BCP 51-16 H6327 | SP000748090 | BCP5116H6327XTSA1 | SOT223 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCP 51-16 H6433 | SP000748092 | BCP5116H6433XTMA1 | SOT223 | | | | none |
| BCP 53-10 H6327 | SP000748122 | BCP5310H6327XTSA1 | SOT223 | | | | none |
| BCP 53-16 H6433 | SP000748126 | BCP5316H6433XTMA1 | SOT223 | | | | none |
| BCP 54-16 H6327 | SP000748130 | BCP5416H6327XTSA1 | SOT223 | | | | none |
| BCP 54-16 H6433 | SP000748132 | BCP5416H6433XTMA1 | SOT223 | | | | none |
| BCP 56-10 H6327 | SP000748366 | BCP5610H6327XTSA1 | SOT223 | | | | none |
| BCP 69-25 H6327 | SP000748374 | BCP6925H6327XTSA1 | SOT223 | | | | none |
| BDP 948 H6433 | SP000748380 | BDP948H6433XTMA1 | SOT223 | | | | none |
| BDP 949 H6327 | SP000748382 | BDP949H6327XTSA1 | SOT223 | | | | none |
| BDP 950 H6327 | SP000748522 | BDP950H6327XTSA1 | SOT223 | | | | none |
| BDP 953 H6327 | SP000748526 | BDP953H6327XTSA1 | SOT223 | | | | none |
| BDP 954 H6327 | SP000748528 | BDP954H6327XTSA1 | SOT223 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BFN 38 H6327 | SP000748530 | BFN38H6327XTSA1 | SOT223 | | | | none |
| BFN 39 H6327 | SP000748532 | BFN39H6327XTSA1 | SOT223 | | | | none |
| BSP 50 H6327 | SP000748534 | BSP50H6327XTSA1 | SOT223 | | | | none |
| BSP 52 H6327 | SP000748886 | BSP52H6327XTSA1 | SOT223 | | | | none |
| BSP 60 H6327 | SP000749082 | BSP60H6327XTSA1 | SOT223 | | | | none |
| BSP 61 H6327 | SP000749562 | BSP61H6327XTSA1 | SOT223 | | | | none |
| BSP 62 H6327 | SP000749564 | BSP62H6327XTSA1 | SOT223 | | | | none |
| PZTA 14 H6327 | SP000749566 | PZTA14H6327XTSA1 | SOT223 | | | | none |
| PZTA 42 H6327 | SP000749568 | PZTA42H6327XTSA1 | SOT223 | | | | none |
| PZTA 92 E6433 | SP000011009 | PZTA92E6433HTMA1 | SOT223 | | | | none |
| PZTA 92 H6433 | SP000749576 | N.A. | SOT223 | | | | none |
| BAL 99 E6433 | SP000010161 | BAL99E6433HTMA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|---------------|-------------|------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BAS 116 E6433 | SP000010196 | BAS116E6433HTMA1 | SOT23 | | | | none |
| BC 848B E6433 | SP000010581 | BC848BE6433HTMA1 | SOT23 | | | | none |
| BC 850B E6327 | SP000010572 | BC850BE6327HTSA1 | SOT23 | | | | none |
| BC 857C E6433 | SP000010660 | BC857CE6433HTMA1 | SOT23 | | | | none |
| BC 858B E6433 | SP000010652 | BC858BE6433HTMA1 | SOT23 | | | | none |
| BC 858C E6327 | SP000010624 | BC858CE6327HTSA1 | SOT23 | | | | none |
| BC 858C E6433 | SP000010654 | BC858CE6433HTMA1 | SOT23 | | | | none |
| BC 859C E6327 | SP000010637 | BC859CE6327HTSA1 | SOT23 | | | | none |
| BCR 116 E6393 | SP000010750 | BCR116E6393HTSA1 | SOT23 | | | | none |
| BCR 141 E6433 | SP000010771 | BCR141E6433HTMA1 | SOT23 | | | | none |
| BCR 148 E6393 | SP000010779 | BCR148E6393HTSA1 | SOT23 | | | | none |
| BCR 169 E6327 | SP000010793 | BCR169E6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 183 E6359 | SP000010801 | BCR183E6359HTMA1 | SOT23 | | | | none |
| BCR 185 E6433 | SP000010807 | BCR185E6433HTMA1 | SOT23 | | | | none |
| BCR 192 E6785 | SP000010815 | BCR192E6785HTSA1 | SOT23 | | | | none |
| BCR 198 E6393 | SP000010818 | BCR198E6393HTSA1 | SOT23 | | | | none |
| BCR 198 E6433 | SP000010820 | BCR198E6433HTMA1 | SOT23 | | | | none |
| BCR 505 E6778 | SP000455114 | BCR505E6778HTSA1 | SOT23 | | | | none |
| BCV 47 E6393 | SP000010868 | BCV47E6393HTSA1 | SOT23 | | | | none |
| BCW 60B E6327 | SP000010551 | BCW60BE6327HTSA1 | SOT23 | | | | none |
| BCW 60D E6327 | SP000010549 | BCW60DE6327HTSA1 | SOT23 | | | | none |
| BCW 60FN E6393 | SP000010569 | BCW60FNE6393HTSA1 | SOT23 | | | | none |
| BCW 61A E6327 | SP000010621 | BCW61AE6327HTSA1 | SOT23 | | | | none |
| BCW 61B E6327 | SP000010629 | BCW61BE6327HTSA1 | SOT23 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-----------------|-------------|--------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCW 61D E6327 | SP000010627 | BCW61DE6327HTSA1 | SOT23 | | | | none |
| BCX 70H E6327 | SP000010550 | BCX70HE6327HTSA1 | SOT23 | | | | none |
| BCX 70H E6433 | SP000010578 | BCX70HE6433HTMA1 | SOT23 | | | | none |
| BCX 71H E6327 | SP000010631 | BCX71HE6327HTSA1 | SOT23 | | | | none |
| MMBD 7000 LT1 | SP000014935 | MMBD7000LT1HTSA1 | SOT23 | | | | none |
| MMBD 914 LT1 | SP000010207 | MMBD914LT1HTSA1 | SOT23 | | | | none |
| MMBT 2222A LT1 | SP000011174 | MMBT2222ALT1HTSA1 | SOT23 | | | | none |
| MMBTA 42 LT1 | SP000010999 | MMBTA42LT1HTSA1 | SOT23 | | | | none |
| SMBT 3904 E6433 | SP000011675 | SMBT3904E6433HTMA1 | SOT23 | | | | none |
| SMBTA 06 E6433 | SP000011688 | SMBTA06E6433HTMA1 | SOT23 | | | | none |
| SMBTA 14 E6327 | SP000010872 | SMBTA14E6327HTSA1 | SOT23 | | | | none |
| BAS 16W H6433 | SP000753168 | BAS16WH6433XTMA1 | SOT323 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-------------------|-------------|---------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BC 817K-16W H6327 | SP000786164 | BC817K16WH6327XTSA1 | SOT323 | none | | | |
| BC 817K-25W H6433 | SP000786166 | BC817K25WH6433XTMA1 | SOT323 | none | | | |
| BC 818K-16W H6327 | SP000746852 | BC818K16WH6327XTSA1 | SOT323 | none | | | |
| BC 847CW H6778 | SP000747286 | BC847CWH6778XTSA1 | SOT323 | none | | | |
| BC 849CW H6327 | SP000747414 | BC849CWH6327XTSA1 | SOT323 | none | | | |
| BC 857BW H6778 | SP000747450 | BC857BWH6778XTSA1 | SOT323 | none | | | |
| BC 858BW H6327 | SP000747582 | BC858BWH6327XTSA1 | SOT323 | none | | | |
| BC 858CW H6327 | SP000747584 | BC858CWH6327XTSA1 | SOT323 | none | | | |
| BC 860BW H6327 | SP000747586 | BC860BWH6327XTSA1 | SOT323 | none | | | |
| BC 860CW H6327 | SP000747588 | BC860CWH6327XTSA1 | SOT323 | none | | | |
| BCR 119W H6327 | SP000755044 | BCR119WH6327XTSA1 | SOT323 | none | | | |
| BCR 129W H6327 | SP000755048 | BCR129WH6327XTSA1 | SOT323 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 142W H6327 | SP000756260 | BCR142WH6327XTSA1 | SOT323 | | | | none |
| BCR 158W H6327 | SP000750762 | BCR158WH6327XTSA1 | SOT323 | | | | none |
| BCR 196W H6327 | SP000757902 | BCR196WH6327XTSA1 | SOT323 | | | | none |
| BAV 70S H6827 | SP000753178 | BAV70SH6827XTSA1 | SOT363 | | | | none |
| BAV 99S H6433 | SP000754048 | BAV99SH6433XTMA1 | SOT363 | | | | none |
| BC 846S H6727 | SP000746928 | BC846SH6727XTSA1 | SOT363 | | | | none |
| BC 847S H6730 | SP001008360 | BC847SH6730XTMA1 | SOT363 | | | | none |
| BC 857S H6827 | SP000747580 | BC857SH6827XTSA1 | SOT363 | | | | none |
| BCM 846S H6327 | SP000747590 | BCM846SH6327XTSA1 | SOT363 | | | | none |
| BCM 856S H6778 | SP000747596 | BCM856SH6778XTSA1 | SOT363 | | | | none |
| BCR 10PN H6730 | SP000750788 | BCR10PNH6730XTMA1 | SOT363 | | | | none |
| BCR 119S H6433 | SP000755042 | BCR119SH6433XTMA1 | SOT363 | | | | none |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-------------------|-------------|----------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCR 135S H6827 | SP000756250 | BCR135SH6827XTSA1 | SOT363 | none | | | |
| BCR 198S H6827 | SP000757908 | BCR198SH6827XTSA1 | SOT363 | none | | | |
| SMBT 3904PN H6327 | SP000749584 | SMBT3904PNH6327XTSA1 | SOT363 | none | | | |
| SMBT 3904S H6327 | SP000749590 | SMBT3904SH6327XTSA1 | SOT363 | none | | | |
| SMBT 3906S H6327 | SP000749596 | SMBT3906SH6327XTSA1 | SOT363 | none | | | |
| BAW 78D H6327 | SP001125530 | BAW78DH6327XTSA1 | SOT89 | none | | | |
| BAW 79D H6327 | SP001125532 | BAW79DH6327XTSA1 | SOT89 | none | | | |
| BCV 28 H6327 | SP001125534 | BCV28H6327XTSA1 | SOT89 | none | | | |
| BCV 29 H6327 | SP001125300 | BCV29H6327XTSA1 | SOT89 | none | | | |
| BCV 49 H6327 | SP001125332 | BCV49H6327XTSA1 | SOT89 | none | | | |
| BCX 51 H6327 | SP001125334 | BCX51H6327XTSA1 | SOT89 | none | | | |
| BCX 51-16 H6433 | SP001125338 | BCX5116H6433XTMA1 | SOT89 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-----------------|-------------|-------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCX 52-16 H6327 | SP001125342 | BCX5216H6327XTSA1 | SOT89 | none | | | |
| BCX 52-16 H6433 | SP001125344 | BCX5216H6433XTMA1 | SOT89 | none | | | |
| BCX 53 H6327 | SP001125346 | BCX53H6327XTSA1 | SOT89 | none | | | |
| BCX 53-10 H6327 | SP001125348 | BCX5310H6327XTSA1 | SOT89 | none | | | |
| BCX 53-16 H6327 | SP001125456 | BCX5316H6327XTSA1 | SOT89 | none | | | |
| BCX 53-16 H6433 | SP001125462 | BCX5316H6433XTMA1 | SOT89 | none | | | |
| BCX 54-16 H6327 | SP001125468 | BCX5416H6327XTSA1 | SOT89 | none | | | |
| BCX 55-16 H6433 | SP001125474 | BCX5516H6433XTMA1 | SOT89 | none | | | |
| BCX 56 H6359 | SP001125478 | BCX56H6359XTMA1 | SOT89 | none | | | |
| BCX 56-16 H6327 | SP001125482 | BCX5616H6327XTSA1 | SOT89 | none | | | |
| BCX 56-16 H6433 | SP001125484 | BCX5616H6433XTMA1 | SOT89 | none | | | |
| BCX 68-10 H6327 | SP001125486 | BCX6810H6327XTSA1 | SOT89 | none | | | |

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!

Product Discontinuation



PD_012_16

!! UPDATE !!

■ Updated Information in **BLUE TYPE**

| | |
|-----------------------|---|
| ■ Last Order Date: | 2019-12-31 2023-12-31 |
| ■ Last Delivery Date: | 2020-12-31 2024-12-31 |

| DISCONTINUED | | | | NEW (REPLACEMENT) | | | |
|-----------------|-------------|--------------------|---------|-------------------|-----------|-----|---------|
| Sales name | SP number | OPN | Package | Sales name | SP number | OPN | Package |
| BCX 68-16 H6327 | SP001125488 | BCX6816H6327XTSA1 | SOT89 | none | | | |
| BCX 69-10 H6327 | SP001125298 | BCX6910H6327XTSA1 | SOT89 | none | | | |
| BCX 69-25 H6327 | SP001125266 | BCX6925H6327XTSA1 | SOT89 | none | | | |
| BFN 18 H6327 | SP001125290 | BFN18H6327XTSA1 | SOT89 | none | | | |
| BFN 19 H6327 | SP001125292 | BFN19H6327XTSA1 | SOT89 | none | | | |
| BC 848BL3 E6327 | SP000013554 | BC848BL3E6327XTMA1 | TSLP-3 | none | | | |

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended!