



## Not Recommended for New Design: LE Series Relays - TMP Type

NRFND.PG0006.12.19.2018

12.19.2018

<b>About This Notice:</b>	The TMP Type LE Series Relays have changed status to Not Recommended For New Design due to possible plans for discontinuation in the future.
<b>Features:</b>	
<b>Effective Date:</b>	Immediate
<b>Affected Parts and/or Replacements:</b>	See attached. There are no direct replacements.
<b>Datasheet(s):</b>	See attached.
<b>Notes:</b>	PCB Type LE Series Relays remain available.