

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20190123000.0 Datasheet for TLV320DAC3203 Information Only

Date: January 28, 2019 **To:** Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN www admin team@list.ti.com).

Sincerely,

PCN Team SC Business Services

Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE TLV320DAC3203IRGET

CUSTOMER PART NUMBER

null

Technical details of this Product Change follow on the next page(s).

PCN Number:		20190123000.0		PCN Date:	January 28, 2019				
Title: Datasheet for TLV320DAC3203									
Custor	mer Contact:	PCN Manage	<u>er</u>		Dep	t:	Quality Services		
Change Type:									
Assembly Site			Design				Bump Site		
Assembly Process			Data Sheet				Bump Material		
Assembly Materials				Part number change			Bump Process		
Mechanical Specification			Test Site			Fab Site			
Packing/Shipping/Labeling			lest Proce	Test Process			Fab Materials		
		Natificatio	n Dotoile		water	Fab Process			
Notification Details Description of Change:									
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details. TEXAS INSTRUMENTS TLV320DAC3203 SLOS756B - MAY 2012 - REVISED DECEMBER 2018									
Changes from Revision A (March 2017) to Revision B									
 Chance 	ged Description of pin	7 in the Pin Fu	nctions table				4		
 Changed Description of pin 7 in the Pin Functions table Changed TYPE and Description of pin 8 in the Pin Functions table 									
Changed PTPE and Description of pin 6 in the PTP Variations table									
Changed pin 21 (ball D1) TYPE From: DVdd To: DVss in the Pin Functions table									
Changed pin 23 (ball B1) TYPE From: IOVdd To: IOVss in the Pin Functions table									
Changed ball C4 TYPE From: I To: I/O in the <i>Pin Functions</i> table									
The datasheet number will be changing.									
Device	e Family		Change	From:		Change To:			
TLV32	20DAC3203			SLOS756	5A		SLOS756B		
These changes may be reviewed at the datasheet links provided.									
http://www.ti.com/product/TLV320DAC3203									
Reason for Change:									
To accurately reflect device characteristics.									
	•						tive / negative):		
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.									
Changes to product identification resulting from this PCN:									
None.									
Product Affected:									
	ODAC3203IRGER	TLV320D	AC3203IRGET	TLV320DAC	3203IY2	ZKR	TLV320DAC3203IYZKT		

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com