



26-Feb-2019

PCN #:P-19-017007

Subject:Manufacturing Location Change of ES1000 tubing products for customers in Asia

Description of Change: Manufacturing location change. This notification is to inform our customers that TE Connectivity will be manufacturing ES1000 tubing products in both our Trutnov and Shanghai facilities. This will enable TE to better serve our customers in Asia and create capacity in our Trutnov plant ready for further growth. The part number list attached shows you the ES1000 products that are affected.

Reason: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you that TE Connectivity will be manufacturing ES1000 tubing products in both our Trutnov and Shanghai facilities. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. We will start to ship ES1000 products from the TE Shanghai facility after 6th June 2019.

Key Dates:

Contact By Date:06-Jun-2019

Implementation Date:06-Jun-2019

Product Affected

CW5088-000

CY1947-000

(Alias Part Numbers:

"ES1000-NO.4-B7-X-55MM"

"3-1899736-1")

Product Affected

193197P022

(Alias Part Numbers:

"6-1191401-5"

"ES1000-NO.1-C1-X-45MM")

CM5359-000

(Alias Part Numbers:

"ES1000-NO.4-B7-X-30MM")

035377P003

(Alias Part Numbers:

"4-1190273-7"

"ES1000-NO.3-B8-X-75MM")

193197P008

(Alias Part Numbers:

"5-1191401-1"

"ES1000-NO.1-C1-X-50MM")

193197P002

(Alias Part Numbers:

"4-1191401-5"

"ES1000-NO.1-C1-X-55MM")

CX7482-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-21MM"

"5-1899719-7")

E84631-000

(Alias Part Numbers:

"7-1200978-7"

"ES1000-NO.4B7X130MMCS7721")

035377P016

(Alias Part Numbers:

"6-1190273-0"

"ES1000-NO.3-B8-X-120MM")

193197P011

(Alias Part Numbers:

"5-1191401-4"

"ES1000-NO.1-C1-X-30MM")

F18778-000

(Alias Part Numbers:

"6-1201322-2"

"ES1000-NO.3-B8-X-80MM")

609564-000

Product Affected

(Alias Part Numbers:

"5-1201145-1"

"ES1000-NO.1-C1-X-150MM")

CR2067-000

C20744-000

(Alias Part Numbers:

"5-1201707-8"

"ES1000-NO.2-B9-X-45MM")

CP4997-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-38MM")

A04375-000

(Alias Part Numbers:

"2-1201147-4"

"ES1000-KIT3-REFILL")

576105P006

(Alias Part Numbers:

"8-1194570-1"

"ES1000-NO.2-A1-X-STK")

576105P009

(Alias Part Numbers:

"8-1194570-4"

"ES1000-NO.2-B9-X-50MM")

555081-000

(Alias Part Numbers:

"2-1197894-9")

085193P005

(Alias Part Numbers:

"9-1190628-7"

"ES1000-NO.4-F3-X-75MM")

193197P021

(Alias Part Numbers:

"6-1191401-4"

"ES1000-NO.1-C1-X-100MM")

CX7481-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-32MM"

"5-1899719-4")

CR7066-000

(Alias Part Numbers:

Product Affected

"ES1000-NO.3-B8-X-30MM"

"7-1899719-9")

035377P006

(Alias Part Numbers:

"5-1190273-0"

"ES1000-NO.3-B8-X-50MM")

085193P006

(Alias Part Numbers:

"9-1190628-8"

"ES1000-NO.4-B7-X-50MM")

576105P002

(Alias Part Numbers:

"7-1194570-7"

"ES1000-NO.2-B9-X-55MM")

193197P003

(Alias Part Numbers:

"4-1191401-6"

"ES1000-NO.1-C1-X-65MM")

085193P004

(Alias Part Numbers:

"9-1190628-6"

"ES1000-NO.4-B7-X-90MM")

CR2066-000

193197P010

(Alias Part Numbers:

"5-1191401-3"

"ES1000-NO.1-C1-X-25MM")

D72328-000

(Alias Part Numbers:

"4-1201146-9"

"ES1000-NO.4-B7-X-150MM")

CM3556-000

(Alias Part Numbers:

"ES1000-NO.4-Z3-X-27MM"

"5-1899413-1")

193197P005

(Alias Part Numbers:

"4-1191401-8"

"ES1000-NO.1-A1-X-STK")

709246-000

Product Affected

(Alias Part Numbers:

"5-1201145-5"

"ES1000-NO.3-B8-X-150MM")

CW3316-000

(Alias Part Numbers:

"2-1899776-3"

"ES1000-NO.3-B8-X-48MM")

EG0206-000

(Alias Part Numbers:

"ES1000-NO.4-F3-X-60MM")

CZ9852-000

(Alias Part Numbers:

"6-1899770-2")

CX7430-000

(Alias Part Numbers:

"ES1000-NO.1-C1-X-19MM"

"5-1899719-5")

C22995-000

(Alias Part Numbers:

"9-1199704-5"

"ES1000-NO.3-B8-X-25MM")

CX7480-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-19MM"

"5-1899719-6")

CR2069-000

085193P014

(Alias Part Numbers:

"1190629-6"

"ES1000-NO.4-F3-X-50MM")

035377P004

(Alias Part Numbers:

"4-1190273-8"

"ES1000-NO.3-B8-X-STK")

D70463-000

(Alias Part Numbers:

"2-1199839-0"

"ES1000-NO.2B9X125MMCS7721")

A85870-000

(Alias Part Numbers:

Product Affected

"3-1201461-2"

"ES1000-NO.4-F3-X-30MM")

035377P008

(Alias Part Numbers:

"5-1190273-2"

"ES1000-NO.3-A1-X-STK")

364171-000

(Alias Part Numbers:

"5-1192730-5"

"ES1000-NO.2-B9-X-100MM")

CR2068-000

CU4597-000

(Alias Part Numbers:

"ES1000-NO.4-B7-X-70MM"

"9-1899652-2")

193197P023

(Alias Part Numbers:

"6-1191401-6"

"ES1000-NO.1-C1-X-35MM")

CL6607-000

(Alias Part Numbers:

"ES1000-NO.3-B8-X-115MM")

E20530-000

(Alias Part Numbers:

"1200424-6"

"ES1000-NO.2-B9-X-40MM")

E65254-000

(Alias Part Numbers:

"5-1201669-1"

"ES1000-NO.4-B7-X-130MM")

A52804-000

(Alias Part Numbers:

"2-1200965-3"

"ES1000-HW-NO.2-O3-X-35MM")

C63832-000

(Alias Part Numbers:

"1-1201146-9"

"ES1000-NO.2-B9-X-150MM")

193197P007

(Alias Part Numbers:

Product Affected

"5-1191401-0"

"ES1000-NO.1-C1-X-20MM")

576105P003

(Alias Part Numbers:

"7-1194570-8"

"ES1000-NO.2-B9-X-65MM")

576105P004

(Alias Part Numbers:

"7-1194570-9"

"ES1000-NO.2-B9-X-STK")

C34252-000

(Alias Part Numbers:

"1200827-7"

"ES1000-NO.3-B8-X-55MM")

CW3317-000

(Alias Part Numbers:

"2-1899776-2"

"ES1000-NO.2-B9-X-48MM")

020920-000

(Alias Part Numbers:

"4-1199943-0"

"ES1000-NO.4-B7-X-100MM")

576105P005

(Alias Part Numbers:

"8-1194570-0"

"ES1000-NO.2-B9-X-75MM")

193197P024

(Alias Part Numbers:

"6-1191401-7"

"ES1000-NO.1-C1-X-40MM")

576105P008

(Alias Part Numbers:

"8-1194570-3"

"ES1000-NO.2-B9-X-25MM")

CX7479-000

(Alias Part Numbers:

"ES1000-NO.1-C1-X-28MM"

"5-1899719-3")

CM3555-000

(Alias Part Numbers:

Product Affected

"ES1000-NO.4-Z3-X-75MM"

"5-1899413-0")

866121-000

(Alias Part Numbers:

"3-1196744-0"

"ES1000-NO.1-C1-X-80MM")

085193P002

(Alias Part Numbers:

"9-1190628-4"

"ES1000-NO.4-B7-X-75MM")

085193P003

(Alias Part Numbers:

"9-1190628-5"

"ES1000-NO.4-B7-X-STK")

D27408-000

(Alias Part Numbers:

"9-1200979-5"

"ES1000-HW-NO.3-M8-X-45MM")

683027-000

(Alias Part Numbers:

"5-1197886-2")

193197P004

(Alias Part Numbers:

"4-1191401-7"

"ES1000-NO.1-C1-X-STK")

A87489-000

(Alias Part Numbers:

"3-1201461-3"

"ES1000-NO.4-F3-X-40MM")

035377P002

(Alias Part Numbers:

"4-1190273-6"

"ES1000-NO.3-B8-X-65MM")

189022-000

(Alias Part Numbers:

"5-1199705-1"

"ES1000-NO.1-C1-X-60MM")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.