

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

Notification# 20190408000.0 Datasheet for BUF634 Information Only

Date: April 09, 2019 **To:** Newark/Farnell PCN

Dear Customer:

This is an information-only announcement of a change to the datasheet for a device that is currently offered by Texas Instruments.

The changes discussed within this notification are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Team (PCN www admin team@list.ti.com).

Sincerely,

PCN Team SC Business Services

Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
BUF634FKTTT	null
BUF634P	null
BUF634T	null
BUF634TG3	null
BUF634U	null
BUF634U/2K5	null
BUF634F/500	null

Technical details of this Product Change follow on the next page(s).

Title: Datasheet for BUF634									
Cu	ustomer Contact: PCN Manager				Dept:		pt:	Quality Services	
Ch	ange Type:								
	Assembly Site			Design				· Bump Site	
Щ	Assembly Process		\square	Data Sheet		Щ		Bump Material	
	Assembly Materials	- 1:	井	Part number c	hange	\underline{H}		Bump Process	
	Mechanical Specific		H	Test Breess		$\frac{\square}{\square}$		Fab Site Fab Materials	
Packing/Shipping/Labeling Test Process						H		· Fab Process	
Notification Details									
De	scription of Change	e:							
Tex	xas Instruments Incor	rporated is a	anno	ouncing an info	rmation only	y no	otificatio	on.	
The	e product datasheet(s	s) is being u	ıpda	ited as summa	rized below.				
The	e following change his	story provid	les f	urther details.					
	le								
4	Texas Instruments							BUF634	
_	INSTRUMENTS				SBO	S030	B-SEPTEM	IBER 2000-REVISED MARCH 2019	
Ch	anges from Revision A (N	lovember 201	5) to	Revision B				Page	
_					Description soct	ione		1	
								tional Amplifier figure 1	
								3	
_	ridded Device Companion	1 10010							
The datasheet number will be changing.									
D	evice Family	Change From:			Change To:				
В	UF634	SBOS030A			SBOS030B				
These changes may be reviewed at the datasheet links provided.									
http://www.ti.com/product/BUF634									
Reason for Change:									
To accurately reflect device characteristics.									
An	ticipated impact on	Fit, Form	, Fu	nction, Quali	ty or Reliab	ilit	y (posi	tive / negative):	
No anticipated impact. This is a specification change announcement only. There are no changes to									
the actual device.									
Changes to product identification resulting from this PCN:									
None.									
Product Affected:									
В	UF634F/500	BUF634F	F/50	00E3 B	UF634FKTTT			BUF634FKTTTE3	
В	UF634P	BUF634F	PG4	В	UF634T			BUF634TG3	
В	UF634U	BUF634l	J/2k	<5 B	UF634UE4				
		<u> </u>		•1		•			

PCN Date:

April 09, 2019

20190408000.0

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
WW PCN Team	PCN www admin_team@list.ti.com

PCN Number: