

OFFICIAL ANNOUNCEMENT
- Discontinuation Note -

TOSHIBA

Please find the **official announcement** that TOSHIBA, in line with previous verbal information, will stop all promotion and sales activities for products in following attachment:

Related products:

BU	P/N	Discontinue date	Phase-Out = last date of order entry	Obsolete = last date of delivery	Substitution level *	Replacement P/N_Company name	Replacement P/N	Reason*
X36	4N25(SHORT,F)	201904	202004	202010	0			3
X36	4N35(SHORT,F)	201904	202004	202010	0			3
X36	TLP126(F)	201904	202004	202010	2	TOSHIBA	TLP182(E(T	3
X36	TLP126(TPL,F)	201904	202004	202010	2	TOSHIBA	TLP182(TPL,E(T	3
X36	TLP126(TPR,F)	201904	202004	202010	2	TOSHIBA	TLP182(TPR,E(T	3
X36	TLP160G(TPL,U,F)	201904	202004	202010	2	TOSHIBA	TLP265J	3
X36	TLP160G(TPR,U,F)	201904	202004	202010	2	TOSHIBA	TLP265J	3
X36	TLP160G(U,F)	201904	202004	202010	2	TOSHIBA	TLP265J	3
X36	TLP160J(TPL,U,C,F)	201904	202004	202010	2	TOSHIBA	TLP265J	3
X36	TLP160J(U,C,F)	201904	202004	202010	2	TOSHIBA	TLP265J	3
X36	TLP161G(T5TL,U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP161G(TPL,U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP161G(TPR,U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP161G(U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP161J(TPL,U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP161J(TPR,U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP161J(U,C,F)	201904	202004	202010	2	TOSHIBA	TLP266J	3
X36	TLP2095(F)	201904	202004	202010	3	TOSHIBA	TLP2395	3
X36	TLP2095(TPL,F)	201904	202004	202010	3	TOSHIBA	TLP2395	3
X36	TLP2098(F)	201904	202004	202010	3	TOSHIBA	TLP2398	3
X36	TLP2098(TPL,F)	201904	202004	202010	3	TOSHIBA	TLP2398	3
X36	TLP2116(TP,F)	201904	202004	202010	1	TOSHIBA	TLP2766A(TP,E(O	2
X36	TLP2118(F)	201904	202004	202010	1	TOSHIBA	TLP2168(F)	2
X36	TLP2118(TP,F)	201904	202004	202010	1	TOSHIBA	TLP2168(TP,F)	2
X36	TLP2200(F)	201904	202004	202010	3	TOSHIBA	TLP2745(E(O	3
X36	TLP2200(LF2,F)	201904	202004	202010	3	TOSHIBA	TLP2745(E(O	3
X36	TLP2200(TP1,F)	201904	202004	202010	3	TOSHIBA	TLP2745(TP,E(O	3
X36	TLP2451(TP,F)	201904	202004	202010	1	TOSHIBA	TLP2451A(TP,F)	2
X36	TLP250(D4,F)	201904	202004	202010	1	TOSHIBA	TLP250H(D4,F)	3
X36	TLP250(D4-TP1,F)	201904	202004	202010	1	TOSHIBA	TLP250H(D4-TP1,F)	3
X36	TLP250(D4-TP5,F)	201904	202004	202010	1	TOSHIBA	TLP250H(D4-TP5,F)	3
X36	TLP250(F)	201904	202004	202010	1	TOSHIBA	TLP250H(F)	3
X36	TLP250(INV,F)	201904	202004	202010	1	TOSHIBA	TLP250H(F)	3
X36	TLP250(LF2,F)	201904	202004	202010	1	TOSHIBA	TLP250HF(F)	3
X36	TLP250(TP5,F)	201904	202004	202010	1	TOSHIBA	TLP250H(TP5,F)	3
X36	TLP250F(INV,F)	201904	202004	202010	1	TOSHIBA	TLP250HF(F)	3
X36	TLP2630(F)	201904	202004	202010	3	TOSHIBA	TLP2768A(E(O	3
X36	TLP2631(F)	201904	202004	202010	3	TOSHIBA	TLP2768A(E(O	3
X36	TLP2631(LF1,F)	201904	202004	202010	3	TOSHIBA	TLP2768A(E(O	3
X36	TLP2631(TP1,F)	201904	202004	202010	3	TOSHIBA	TLP2768A(TP,E(O	3
X36	TLP331(BV-LF1,F)	201904	202004	202010	3	TOSHIBA	TLP383(BL,E(T	3
X36	TLP331(BV-TP1,F)	201904	202004	202010	3	TOSHIBA	TLP383(BL,E(T	3

X36	TLP331(F)	201904	202004	202010	3	TOSHIBA	TLP383(E(T	3
X36	TLP332(F)	201904	202004	202010	3	TOSHIBA	TLP383(E(T	3
X36	TLP371(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(O	3
X36	TLP371(TP1,F)	201904	202004	202010	2	TOSHIBA	TLP627M(TP1,E(O	3
X36	TLP372(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(O	3
X36	TLP512(F)	201904	202004	202010	3	TOSHIBA	TLP2719(E(O	3
X36	TLP523(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(O	3
X36	TLP523-2(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(Ox2	3
X36	TLP523-4(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(Ox4	3
X36	TLP550(F)	201904	202004	202010	3	TOSHIBA	TLP2719(E(O	3
X36	TLP550(LF1,F)	201904	202004	202010	3	TOSHIBA	TLP2719(E(O	3
X36	TLP550(O,F)	201904	202004	202010	3	TOSHIBA	TLP2719(E(O	3
X36	TLP550(O-LF2,F)	201904	202004	202010	3	TOSHIBA	TLP2719(E(O	3
X36	TLP570(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(O	3
X36	TLP624-2(BV,F)	201904	202004	202010	3	TOSHIBA	TLP383(BL,E(Tx2	3
X36	TLP624-2(F)	201904	202004	202010	3	TOSHIBA	TLP383(E(Tx2	3
X36	TLP624-4(BV,F)	201904	202004	202010	3	TOSHIBA	TLP383(BL,E(Tx4	3
X36	TLP624-4(F)	201904	202004	202010	3	TOSHIBA	TLP383(E(Tx4	3
X36	TLP627-2(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(Ox2	3
X36	TLP627-2(TP1,F)	201904	202004	202010	2	TOSHIBA	TLP627M(TP1,E(Ox2	3
X36	TLP627-4(F)	201904	202004	202010	2	TOSHIBA	TLP627M(E(Ox4	3
X36	TLP733F(D4,M,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP733F(D4-C173,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP733F(D4-C174,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP734(D4-C173,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP734(D4-GB,M,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP734(M,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP734F(D4-C173,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TLP734F(D4-GR,M,F)	201904	202004	202010	3	TOSHIBA	TLP383orTLP785	3
X36	TOCP200QK	201904	202004	202010	0			5
X36	TORX1850(F)	201904	202004	202010	0			4

Substitution level:

0 No replacement P/N

1 Package and characteristics are mostly same or better, not necessary to change other circuit to replace

2 Package and characteristics are mostly same or better, but some modification of the other circuit is necessary

3 Characteristics are same or better, but package/pin arrangement are different, so the other circuit modification is necessary

Reason:

2 Chip Shrink

3 Integration of products

4 Discontinuation of Assembly Machine

5 No Order Forecast

Discontinuation schedule:

1) Official announcement to customer 29.04.2019

2) Last date of order entry to Toshiba's local Sales Office in April 2020

3) Last date of delivery to customer in October 2020

Date 29.04.19

generated by M. Diephaus – Senior Manager

Toshiba local Sales Office

.....
(document transmitted by E-Mail, valid without signature)