



12-Jun-2019

PCN #:P-19-017496

Subject:Manufacturing Location Change Appliances Tubing HF Products

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from Menlo Park, USA to Trutnov, CZ. Different parts will move in different phases, consequently not all new part numbers will be immediately available at the end of the notification period.

Reason: Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery. Upon request, a PPAP Level 2 will be available if it concerns a transfer of a process which produces a finished TE-product.

Key Dates:

Contact By Date:02-Sep-2019

Implementation Date:02-Sep-2019

Product Affected

CB5086-000

CB5095-000

(Alias Part Numbers:

"1-1899224-1")

CS8789-000

CM7400-000

932907N002

(Alias Part Numbers:

"6-1197230-8"

"HF-07FRX25-CS7552")

Product Affected

CP9272-000

(Alias Part Numbers:

"HF-07FRX4/NM")

CS8792-000

(Alias Part Numbers:

"HF-04FRX4/NM")

CB5079-000

CB5088-000

(Alias Part Numbers:

"1-1899833-3")

CB5092-000

(Alias Part Numbers:

"5-1899229-9")

CL0854-000

CF6152-000

CN9258-000

CB5083-000

(Alias Part Numbers:

"HF-07FRX100"

"1-1899833-1")

CB5080-000

(Alias Part Numbers:

"9-1899832-6")

CS8788-000

CF7300-000

(Alias Part Numbers:

"5-1899235-0"

"HF-17FRX4")

CB5087-000

(Alias Part Numbers:

"9-1899207-4"

"HF-07FRX4")

CB5094-000

CL4195-000

(Alias Part Numbers:

"HF-17FRX25-CS7552")

CB5091-000

(Alias Part Numbers:

"1-1899833-5")

CB5093-000

Product Affected

(Alias Part Numbers:

"1-1899833-6")

CB5096-000

(Alias Part Numbers:

"1-1899833-7")

CB5078-000

(Alias Part Numbers:

"HF-04FRX100")

CB5081-000

CB5084-000

CB5082-000

(Alias Part Numbers:

"9-1899832-7")

CS8791-000

(Alias Part Numbers:

"HF-07FRX100/NM"

"1899833-3")

CB5090-000

(Alias Part Numbers:

"1-1899833-4")

CB5089-000

CS8790-000

CB5085-000

(Alias Part Numbers:

"1-1899833-2")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.