



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M000968

DATE: 21-Jun-2019

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS1818R-20-U+	N/A			Part reactivated from prior notice: M000969I
Reactivation	DS28EL15X+U	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX16931BAGLS/VY+	N/A			Part reactivated from prior notice: M000875
Reactivation	MAX16931BAGLS/VY+T	N/A			Part reactivated from prior notice: M000875
Reactivation	MAX19586ETN+D	N/A			Part reactivated from prior notice: M000963I
Reactivation	MAX19588ETN+D	N/A			Part reactivated from prior notice: M000969I
Reactivation	MAX20307DEMBD#	N/A			Part reactivated from prior notice: M000948I
Reactivation	MAX2694EWS+	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX2694EWS+T	N/A			Part reactivated from prior notice: M000965I
Reactivation	MAX6071AAUT30+	N/A			Part reactivated from prior notice: M000969I
Lead-Free Conversion	STM1E-SFP24	N/A	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT251AFQ-ADJ-008	N/A	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT251AFQR-ADJ-008	N/A	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT255BFQN-ADJ	VT255BFQX-ADJ	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT261ABWFQR-ADJ	VT261ABWFQX-ADJ	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT266BWFQ-ADJ	N/A	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT266WFQ-ADJ-008	VT266WFQ-ADJ	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT7505FQ-ADJ	N/A	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Lead-Free Conversion	VT7505FQX-ADJ	N/A	20-Jun-2020	19-Dec-2020	Part can no longer be manufactured
Discontinuance	IC0400C782SF+LTB	N/A	20-Jun-2020	20-Dec-2020	Part can no longer be manufactured
Discontinuance	MAX14713EWL+TCKA	MAX14713EWL+T	20-Jun-2020	20-Dec-2020	Part can no longer be manufactured
Discontinuance	MAX20307EVKIT#	N/A	21-Jun-2019	21-Jun-2019	EVKIT is No Longer Supported
Discontinuance	MAX20307EWL+T	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	MAXM17502ALI+	MAXM17502ALI#	21-Jun-2019	21-Jun-2019	The part was not released
Discontinuance	MAXM17502ALI+T	MAXM17502ALI#T	21-Jun-2019	21-Jun-2019	The part was not released
Discontinuance	STM1E-SFP22	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Jul-2019

Discontinuance	STM1E-SFP23	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	STM1E-SFP26	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1156SAFQR	VT1156SAFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1165SFQR	VT1165SFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1175MAFPR	VT1175MAFPX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1175SFQR	VT1175SFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1185MFPR	VT1185MFPX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1189SAFQR	VT1189SAFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1195SFQR-001	VT1195SFQX-001	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1198SBFQR	VT1198SBFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1526MBFQR	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1536MBFQR	VT1536MBFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1547MBFQR	VT1547MBFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1577MAFQR	VT1577MAFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1626SFQR	VT1626SFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT1656SAFQR	VT1656SAFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT233TFCR-ADJ	VT233TFCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT233WFCX-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT238AWFQR-ADJ	VT238AWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT241WFCR-ADJ	VT241WFCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT242WFCR-ADJ	VT242WFCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT243WFCR-ADJ	VT243WFCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT245ABWFQR-ADJ	VT245ABWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT245AWFQR-ADJ	VT245AWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT246BWFQR-ADJ	VT246BWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT247BWFQR-ADJ	VT247BWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT247WFQR-ADJ	VT247WFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT248BWFQ-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT248BWFQR-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT248BWFQX-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT2491FCR-ADJ	VT2491FCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT2492AFQR-ADJ	VT2492AFCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT251AFQR-ADJ	VT251AFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT255FQN-ADJ	VT255FQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT260WFQR-ADJ	VT260WFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT261BWFQR-ADJ	VT261BWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 22-Jul-2019**

Discontinuance	VT263ABWFQR-ADJ	VT263ABWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT263AWFQR-ADJ	VT263AWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT263BWFQR-ADJ	VT263BWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT263WFQR-ADJ	VT263WFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT266AWFQR-ADJ	VT266AWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT267AWFQR-ADJ	VT267AWFQX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT271MFP	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT271MFPR	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT271MFPX	N/A	21-Dec-2019	20-Dec-2020	Part can no longer be manufactured
Discontinuance	VT271SFQR	VT271SFQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT281BFCR-ADJ	VT281BFCX-ADJ	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT285FQN-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT285FQR-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT285FQX-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT500FQR	VT500FQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT501FQR	VT501FQX	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured
Discontinuance	VT7505FQR-ADJ	N/A	21-Jun-2019	21-Jun-2019	Part can no longer be manufactured