



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000973I

DATE: 20-Jul-2019

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	5962-88503012C	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	5962-9073102M2C	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	5962-9312502M2C	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0504-30+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0504-30+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0507-32+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	806-0507-32+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	8100604EA	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	8100616EA	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG200C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG201ACSE+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG300C/W	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG300C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG305C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG406C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG407C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG408DY+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG409DY+TG52	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG411DY+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG411DY+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG413DY+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG419DY+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG419DY+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG441DY+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG442CY+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DG529CWN+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	DS1091LUA-040+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1100U-75+T&R	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1413#	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1831BS-T&R+C03	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS18B20-SL+TCKJ	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS1990A-F5-ECB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2431P-045-A02+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2433X-300-EC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS26514G+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2704RG-CC1+T&R	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2704RQ-C0A+T&R	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS2704RQC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-001-11+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-001-11+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0N+1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0N+1T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0P+1T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0Q+1T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0R+2T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E01P-W0R+3T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28E15X-S+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28EB00P+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS28EB00P+T&R	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS33W41+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS33X161+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DS33X41+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSHB1Q01+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSHB1Q01+T10	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSK4X+U	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSQ3301-K01+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	DSQ33G1+M00	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7642ECPD+G52	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7660CSA+G002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7660CSA+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7662CBA+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7662E/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	ICL7663ACSA+TG55	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICL7665ESA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7211AC/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7212AMC/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7212C/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7218CC/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7218DC/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7225C/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	ICM7555ISA+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1021BETX+T	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX1026BEEE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1043BETX+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1043BETX+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1082ACUE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1085ACSA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1091BCEI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11044BECB+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11068GUU/V+G0K	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11068GUU/V+TG0K	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1121EGK+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1121EGK+TD	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11290EWX+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11290EWX+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX11801EWC+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX12001ETB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX12001ETB+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1245BCAP+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX13342EETD+TG40	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX13444EASA+TG071	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14526EEWP+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14526EEWP+CC6	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14526EEWP+CJ8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14526EEWP+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14526EEWP+TCJ8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1452EAE+C8H	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14534EEWC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX14534EEWC+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14540AEEWP+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14540AEEWP+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14540EEWP+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14547AEUT+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14547AEUT+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14550AEETB+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14560EWC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14577EEWA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14577EEWA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14580EETE+C77	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14580EETE+CCE	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14580EETE+TC77	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14580EETE+TCCE	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14587EEWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14589EEWL+G2B	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14592EEWE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14593EEWV+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14593EEWV+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14598EEWV+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14598EEWV+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14599EEWV+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14599EEWV+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14603ETA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14603ETA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14617ETA+GH7	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14617ETA+TGH7	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14629EETJ+CCA	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14629EETJ+TCCA	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14638EZA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14639EZA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14639EZA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14646EEWE+G2B	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14646EEWE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14646EEWE+TG2B	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14648AEWA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX14648AEWA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14660EZL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14660EZL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14675CESE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14675CESE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14675CETE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14675CETE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14675ESE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14677EZA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14679EEWV+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14679EEWV+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14701EWC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14701EWC+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14709ENL+CGZ	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14710ENC+CH0	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14710ENC+TCH0	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14729EEWV+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14729EEWV+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1480BCPI+G002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14810CTU+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX14810CTU+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15041ETE+C90	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15041ETE+TC90	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15066EWE+G1D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15066EWE+TG1D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15120GTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15120GTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX152CPP+CE0	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15301AC00+CJB	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15301AC00+TCJB	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15301AD00+CJF	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15301AD00+TCJF	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1532AETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1532AETL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1532AETL+TG075	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15411TGTM+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX15411TGTMT+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1546AETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1547AETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15511VGTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15511VGTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15561CGTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15561CGTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15566TGTG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15567GTG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15567GTG+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15588GTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX15588GTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16014TT+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16033LLB31+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16076ATP+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16076ATP+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16076ATP/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16076ATP/V+CJV	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16076ATP/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16076ATP/V+TCJV	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AUR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR16O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR16O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR29O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR29O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR31O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081AXR31O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR29O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR29O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR29Q+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR29Q+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR30Q+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR30Q+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081UR31O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX16081UR31O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR10A+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR10A+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR28A+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR28A+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR28Q+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR28Q+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR29Q+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR29Q+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR30A+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16081XR30A+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082AUR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082AXR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082UR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082UR38U+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082UR38U+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082XR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082XR17N+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082XR17N+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082XR38U+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16082XR38U+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AUR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR17O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR17O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR29E+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR29E+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR31O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083AXR31O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR16N+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR16N+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR16O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR16O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR31O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083UR31O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX16083XR100+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR100+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR11B+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR11B+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR29E+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR29E+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR31L+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR31L+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR322+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR322+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR46V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16083XR46V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084AUS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084AXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084AXS17B+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084AXS17B+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084US+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084XS16H+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084XS16H+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084XS16P+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16084XS16P+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16085AUS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16085AXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16085US+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16085XS29H+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16085XS29H+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AUS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS29B+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS29B+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS29O+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS29O+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS31W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086AXS31W+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086US+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086US16N+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX16086US16N+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086US33H+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086US33H+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086US46N+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086US46N+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086XS29G+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16086XS29G+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16087AUS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16087AXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16087US+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16087XS17H+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16087XS17H+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16088AUS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16088AXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16088US+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16088XS44F+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16088XS44F+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089AUS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089AXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089AXS+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089US+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089US29L+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089US29L+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089XS46L+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16089XS46L+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16091UK31BMA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16091UK31BMA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16092UK29HOA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16093UK19HOB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16094UK16F+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16095UK22HOB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16096UK44L+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16102A1707+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16102A1707+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16131WTNN00+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16131WTNN16+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX16131WTNN16+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16908XAUE50/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16908XAUE50/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16931ATLR/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16943EGEE/V+CLU	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16951AUE/V+CHZ	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16951AUE/V+TCHZ	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16958GEE/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16958GEE/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16959GEE/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16959GEE/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16963RAUEA/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16963RAUEA/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16970GTEB/V+	MAX16970AGTEB/V+	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16970GTEB/V+T	MAX16970AGTEB/V+T	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16971GEEB/V+	MAX16971AGEEB/V+	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16971GEEB/V+T	MAX16971AGEEB/V+T	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16980GEE/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16980GEE/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16981GEE/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX16981GEE/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17007BGTI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17009GTL+TG40	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17010AETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17010AETL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17010AETL+TGA3	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17010ETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17010ETL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17010ETL+TGA3	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17018BAGL/VY+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17018BAGL/VY+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17018CATL/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17018CATL/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17018DAGL/VY+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17018DAGL/VY+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+CCM	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX17020ETJ+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TGB4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17020ETJ+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17021GTL+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17021GTL+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17023CAUI/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17023CAUI/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17028GTJ+G1D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17028GTJ+TG1D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17033GTL+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17043G+TG075	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17051X+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17051X+T10	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17079GTL+G0Y	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17079GTL+TG0Y	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17087GTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17087GTL+TG38	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17139ETL+C51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17139ETL+TC51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17175ETG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17175ETG+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17408GTI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17408GTI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17412ETI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17428GTJ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17428GTJ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17428GTJ+TG40	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17434GTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17434GTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17511TGTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17511TGTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17611GTL+G2Z	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17611GTL+TG2Z	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX17841GUE+T	MAX17841BGUE+T	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE/V+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE/V+CEN	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX17841GUE/V+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1870AETJ+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1907AETL+TG069	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1907AETL+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1907AETL+TG50	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1907AETL+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1907AETL+TGB4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1907AETL+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX19681EXW+D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1987ETM+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1987ETM+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1988ETM+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1988ETM+TG075	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX1988ETM+TG40	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX19997AETX+G126	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX19997AETX+TG126	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX20091ATM/V+GE	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX20091ATM/V+TGE	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX202EESE+TG074	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2070GTM+CJ4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2070GTM+TCJ4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2151BETJ/V+CL2	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2151BETJ/V+TCL2	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX2151BETJ/V+WCL3	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3030EESE+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3032ECUE+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3072EESA+TG11	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3072EESA+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3094EEUE+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31782ETL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31916AUI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX31916AUI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3207EAUT+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX3209EEUU+TG48	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3225EETP+TGH7	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX3244ECAI+TG035	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3245EEAI+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3245EEUI+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3322EEUP+C5R	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3323EEUE+GA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3344EEUE+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3377EETD+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3378EETD+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3378EETD+TG071	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3387EEUG+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3391EEUD+TG11	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3397EELA+GA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3397EELA+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3456EETE+TG126	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3642E/D-B0X	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3646ETG+C86	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3721UTG+	MAX3727CTE+	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3721UTG+T	MAX3727CTE+	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3721UTG+TG104	MAX3727CTE+T	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3721UTG+TGA8	MAX3727CTE+T	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3722UTJ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3722UTJ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX3845UCQ+TDG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4210BEUA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281FANS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281FANS+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281HANS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281HANS+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX44281TANS+	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX44281TANS+T	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX44281UANS+T	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX44281VANS+	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX44281VANS+T	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX4546CEE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX4550CWI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4572CAI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4605ESE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4605ESE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4754ETE+TG104	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4754ETE+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4758EWX+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4787EXK+C7Q	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4814EECB+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4824ETP+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4824ETP+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4865ELT+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4888BGTI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4888BGTI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4889ETO+G126	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4928AETN+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4928BETN+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4929EETP+CFS	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4929EETP+TCFS	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4983EEVB+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX4983EEVB+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5394LANA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5394LANA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5457EEE+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5859AEXW+D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5881CXW+D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5968ITI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5968ITI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX5969EETE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6314US31D1+C3T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6315US45D2+	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX6315US45D2+T	N/A	20-Jul-2019	20-Jul-2019	The part was not released
Discontinuance	MAX6381LT31D1+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6381LT31D1+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6387LT23D3+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6427MRUR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX642AESA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6461XR27+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6642ATT96+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6711LEXS+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6736XKSVD3+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6736XKSVD3+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6808UA26+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6808UA26+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6866UK23D1S+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX6868UK23D1S+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX708MSA/PR+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77270AEWL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77270AEWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77271EWL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77271EWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77660AEVV+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77660AEVV+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77686AEWE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77686AEWE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77693GEWQ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77693GEWQ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77696EWI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77696EWI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77802AEWW+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77802AEWW+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77802EWW+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77802EWW+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77803GEWJ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77803GEWJ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819EWB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819XEWB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819ZEWB+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77819ZEWB+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77823EWZ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77823EWZ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX77888EWJ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX77888EWJ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX797C/W+G0F	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8211C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX860MSA/PR2+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX860MSA/PR2+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT13+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT13+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT16+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT18+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT19+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT19+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT25+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT25+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YELT82+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT08+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT08+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT10+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT10+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT11+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT11+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT16+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT24+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8640YEXT24+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8670AETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8670AETL+TG069	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8671CETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8671CETL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8671CETL+TG069	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8677AETG+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8677AETG+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8680CETL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8680CETL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8680ETL+B4M	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8680ETL+C7F	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8680ETL+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8694LEWG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX8694LEWG+CB7	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8694LEWG+CD5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8694LEWG+GF3	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8694LEWG+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8694LEWG+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8698EWO+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8698EWO+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8770GTL+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8770GTL+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8770GTL+TG29	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8770GTL+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8770GTL+TGB4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8770GTL+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8771GTL+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8772GTL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8772GTL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8772GTL+TG40	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8774GTL+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8774GTL+TGB4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8774GTL+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8776GTJ+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8776GTJ+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8778ETJ+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8791GTA+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8791GTA+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8792ETD+G1D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8792ETD+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8792ETD+TG1D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8792ETD+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8792ETD+TGB4	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8792ETD+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8799GTI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8799GTI+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8839ERE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8839ERE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8839XEREE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX8839XEREE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8841ELT33+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8857AETL+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8858ETJ+G05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8858ETJ+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8863TMUK/PR3+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8863TMUK/PR3+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8899EWZ+TCAA	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8899GEWZ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8899GEWZ+C62	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8899GEWZ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8899GEWZ+TC62	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8907CEWN+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8907CEWN+CDH	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8907CEWN+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8907CEWN+TCDH	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8925EWN+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8925EWN+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8946EWL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8946EWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8951EWC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8951EWC+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8955E/DW+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8959EWG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8959EWG+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8968EWL+CBF	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8968EWL+TCBF	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+C98	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+C9A	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+CBL	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+CCC	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+CDD	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+TC98	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+TC9A	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX8976EEWA+TCBL	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+TCCC	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8976EEWA+TCDD	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8981EWZ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8981EWZ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8981MEWZ+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8981MEWZ+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+CAW	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+TCAW	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8983EWE+TCAX	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8985EWX+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8985EWX+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8986EWG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8986EWG+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8989EWL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8989EWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8994EWO+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8994EWO+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8994MEWO+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8994MEWO+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8997EWW+C59	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8997EWW+TC59	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8997EWW+TWC59	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8997EWW+WC59	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8999EWG+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8999EWG+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8999YEXT15+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8999YEXT15+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX8999YEXT18+TCG6	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9249GCM/V+CNT	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9249GCM/V+TCNT	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9312ETJ+GH7	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9312ETJ+TGH7	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9372EKA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX9526AEI/V+C68	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9526AEI/V+TC68	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9550EZK+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9652ASA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9705AETB+TC4S	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9705BETB+C4S	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9705BETB+G05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9705BETB+TC4S	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9705BETB+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9705BETB+TG24	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9715ETE+TG104	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9715ETE+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9715EUE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEBC+TG50	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AETC+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AETC+TG104	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AETC+TG19	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AETC+TGC1	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724AEUD+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+TG47	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+TG50	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BEBC+TGD6	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BETC+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BETC+TG104	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BETC+TG126	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BETC+TG51	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9724BETC+TGA8	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98330ETA+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98330ETA+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98330EWL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Aug-2019

Discontinuance	MAX98330EWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98334EWL+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98334EWL+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98700ETE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98700ETE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98702ETE+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX98702ETE+T	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9911EXT+TG50	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9915EXT+TG05	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAX9915EXT+TG071	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-0000+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2549+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2553+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2557+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2570+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2576+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2577+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-2612+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MAXQ622X-UEI+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX574ALEWI+CDR	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX574ALEWI+TCDR	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7225C/D	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7225C/W+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7226KP+G002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7528KCWP+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7528KCWP+TG126	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7528KEQP+TG002	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MX7541AKEWN+TGA5	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	MXD1815UR31+	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured
Discontinuance	TSC427IJA	N/A	20-Jul-2019	18-Jan-2021	Part can no longer be manufactured