



17-Oct-2019

PCN #:P-19-018093

Subject:Manufacturing Location Change Appliances Tubing SST Products

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from Menlo Park, USA to Trutnov, CZ. This notification is to inform our customers that TE Connectivity is closing our Menlo Park facility in USA and moving the production to our Trutnov facility in Czech Republic. The receiving facility in Trutnov is already an established Heat Shrinkable Tubing manufacturing site.

Reason: Dear Customer, we hereby inform you about a transfer of processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard automotive requirements. As part of the production move, we will start to ship SST products after 15th January 2020 from the Trutnov facility. After this date TE reserves the right to provide qualified products from any of the manufacturing locations during this transfer. As not all part numbers will transfer at the same time customers may still receive Products from the Menlo Park location after this transfer date due to inventory. . Where necessary TE will continue with internal qualification and testing of products after they are received at the new locations.

Key Dates:

Contact By Date:15-Jan-2020

Implementation Date:15-Jan-2020

Product Affected

CN2239-000

CM0192-000

CM5886-000

CF8124-000

CL5081-000

Product Affected

(Alias Part Numbers:
"SST-6-13/FR/97/NM"
"5-1899833-7")

081350-001

(Alias Part Numbers:
"7-1200272-5"
"SST-6-07/FR-RSU")

CB5426-000

CB5337-000

CZ7028-000

(Alias Part Numbers:
"SST-4-15/FR/97")

CM3305-000

CF3734-000

934125-001

(Alias Part Numbers:
"7-1197238-1"
"SST-48-15/FR/RED/97")

367154-001

(Alias Part Numbers:
"3-1200271-3"
"SST-12-27/FR-RSU")

CB5310-000

CB5383-000

CB5275-000

CB5399-000

CB5342-000

CB5428-000

(Alias Part Numbers:
"SST-9-20/226"
"2-1899833-9")

CL4283-000

CB5304-000

CB5325-000

375086-001

(Alias Part Numbers:
"9-1192809-1")

CB5363-000

CL0859-000

(Alias Part Numbers:

Product Affected

"SST-48-04/FR/97")

CM6498-000

CB5286-000

CB5271-000

CB5413-000

CB5377-000

CZ3677-000

296259-001

(Alias Part Numbers:

"2-1192244-8"

"SST-48-07/FR/97OBS")

CB5340-000

CF3733-000

CB5289-000

(Alias Part Numbers:

"SST-12-17/FR/97"

"5-1899230-3")

EM84462001

CB5352-000

101059-001

(Alias Part Numbers:

"6-1190739-7"

"SST-15-11/FR/97")

CB5305-000

CB5290-000

252137-001

(Alias Part Numbers:

"1191847-5"

"SST-48-15/FR/97")

CB5278-000

144867-001

(Alias Part Numbers:

"3-1191047-0"

"SST-18-17/RS")

CJ2132-000

(Alias Part Numbers:

"SST-48-17/97"

"4-1899833-4")

CB5333-000

841214-001

Product Affected

(Alias Part Numbers:

"1196563-7"

"SST-12-20/FR/97")

182084-001

(Alias Part Numbers:

"8-1200271-8"

"SST-18-45/FR-RSU")

CN2241-000

CB5420-000

CB5369-000

CB5404-000

CB5277-000

CB5353-000

CN2240-000

922030-001

(Alias Part Numbers:

"1-1197154-6"

"SST-27-20/FR/RED/97")

CB5398-000

CN2236-000

CB5316-000

CB5336-000

CB5341-000

086815-001

(Alias Part Numbers:

"5-1190640-3"

"SST-48-20/FR/97")

CW8339-000

CZ6033-000

(Alias Part Numbers:

"SST-3-11/FR/97")

CB5270-000

CB5417-000

CB5296-000

(Alias Part Numbers:

"9-1899238-3"

"SST-12-27/97")

CB5374-000

CB5366-000

817881-001

Product Affected

(Alias Part Numbers:

"2-1196373-9"

"SST-4-15M/FR/97")

855609-001

(Alias Part Numbers:

"1-1196669-2"

"SST-48-20M/FR/97")

CB5423-000

CN2238-000

CB5362-000

CB5273-000

EF9758-000

(Alias Part Numbers:

"SST-48-27/FR/97/NM")

CB5393-000

CB5317-000

CS9367-000

(Alias Part Numbers:

"SST-48-04/FR/97/NM"

"1899833-4")

CB5343-000

CB5425-000

CJ0285-000

CP1728-000

(Alias Part Numbers:

"SST-24-45/FR/97/NM")

CM9131-000

CN2237-000

CB5372-000

(Alias Part Numbers:

"SST-48-15/97")

CX0637-000

(Alias Part Numbers:

"SST-6-11/FR/RED/97")

CL4309-000

CZ3651-000

(Alias Part Numbers:

"1196589-5")

CB5406-000

(Alias Part Numbers:

Product Affected

"SST-6-04/97"

"6-1899222-4")

CB5378-000

CB5272-000

(Alias Part Numbers:

"SST-12-07/226"

"3-1899241-7")

058441-001

(Alias Part Numbers:

"6-1190443-7"

"SST-20-27/RS/SM")

CL6755-000

(Alias Part Numbers:

"SST-48-04/97")

CJ4707-000

(Alias Part Numbers:

"SST-24-27/FR/97/NM")

CB5322-000

CB5402-000

CW5551-000

(Alias Part Numbers:

"SST-3-13/FR/97")

CB5335-000

CB5397-000

CB5334-000

(Alias Part Numbers:

"3-1899241-6"

"SST-48-07/FR/97")

CM0193-000

CB5283-000

885873-001

CB5282-000

(Alias Part Numbers:

"SST-12-13/226"

"5-1899224-3")

CB5291-000

CB5403-000

(Alias Part Numbers:

"SST-6-03/FR/97"

"3-1899222-4")

Product Affected

CZ2400-000

(Alias Part Numbers:

"SST-48-20/97"

"3-1899832-6")

CM4448-000

CB5367-000

(Alias Part Numbers:

"1899274-2")

342621-001

(Alias Part Numbers:

"5-1192581-8"

"SST-9-27/FR/WHT/97")

695839-001

(Alias Part Numbers:

"9-1195458-2"

"SST-48-11/FR/97")

CF3964-000

CM0194-000

CF5668-000

CB5301-000

(Alias Part Numbers:

"SST-18-45/FR/97"

"5-1899214-7")

CB5346-000

CB5309-000

CB5354-000

A95364-001

(Alias Part Numbers:

"9-1200272-6"

"SST-6-04/FR-RSU")

919338-001

(Alias Part Numbers:

"1-1197134-6"

"SST-6-07M/FR/97")

CM2026-000

(Alias Part Numbers:

"SST-48-04/FR/RED/97")

CB5411-000

(Alias Part Numbers:

"SST-6-07/FR/97"

Product Affected

"5-1899230-4")

CJ9434-000

(Alias Part Numbers:

"SST-48-15/FR/YLW/97")

CB5274-000

CL8044-000

(Alias Part Numbers:

"SST-3-15/97")

348503-001

(Alias Part Numbers:

"4-1192622-3"

"SST-9-27/FR/RED/97")

CB5284-000

CB5370-000

CB5339-000

CB5338-000

125178-001

(Alias Part Numbers:

"9-1190909-8"

"SST-12-11/FR/97")

216663-001

(Alias Part Numbers:

"4-1191581-3")

014251-001

(Alias Part Numbers:

"5-1190111-3"

"SST-48-11/FR/WHT/97")

EG7054-000

CB5371-000

CB5351-000

CB5407-000

(Alias Part Numbers:

"6-1899253-7"

"SST-6-04/FR/97")

CB5328-000

CB5330-000

CB5297-000

(Alias Part Numbers:

"SST-12-27/FR/97"

"7-1899279-6")

Product Affected

CB5348-000

CF9842-000

(Alias Part Numbers:

"SST-1.57-07/226/RED/NM")

CL1602-000

CB5355-000

CB5288-000

CF3967-000

(Alias Part Numbers:

"SST-48-11/226-CS8747")

476049-001

(Alias Part Numbers:

"5-1193565-5"

"SST-48-15/FR/WHT/97")

CB5385-000

CS2969-000

CB5401-000

CB5360-000

CB5400-000

CB5408-000

172896-001

(Alias Part Numbers:

"8-1200271-2"

"SST-12-17/FR-RSU")

CB5368-000

439789-001

(Alias Part Numbers:

"8-1193304-1")

CB5412-000

CB5390-000

CN0369-000

CM4520-000

757555-001

(Alias Part Numbers:

"1-1195903-7"

"SST-27-20/FR/WHT/97")

CB5331-000

(Alias Part Numbers:

"SST-48-07/226/NM")

CL0858-000

Product Affected

(Alias Part Numbers:

"SST-48-03/FR/97")

CB5324-000

CB5422-000

CL2384-000

CM8156-000

CB5295-000

CB5364-000

CB5410-000

CR2746-000

039676-001

(Alias Part Numbers:

"4-1190303-8"

"SST-27-20/FR/97")

EG4905-000

(Alias Part Numbers:

"SST-48-03/FR/97/RED")

CB5418-000

EF9757-000

(Alias Part Numbers:

"SST-48-17/FR/97/NM")

CM5358-000

(Alias Part Numbers:

"SST-14-45/FR/97/NM"

"SST-14-45/FR/97/NM")

CB5347-000

CB5416-000

(Alias Part Numbers:

"2-1899309-2")

CB5419-000

731405-001

(Alias Part Numbers:

"1-1195714-5"

"SST-15-11OE/AP/RS3")

CM2028-000

(Alias Part Numbers:

"SST-48-11/FR/YLW/97")

CB5349-000

CF3966-000

(Alias Part Numbers:

Product Affected

"SST-48-17/226-CS8748")

CS4237-000

591105-001

(Alias Part Numbers:

"8-1194675-8"

"SST-30-04/FR/97")

EK2635-000

(Alias Part Numbers:

"SST-9-11/226")

CB5387-000

083487-001

(Alias Part Numbers:

"2-1190617-2"

"SST-9-27/FR/97")

CW5552-000

(Alias Part Numbers:

"SST-4-17/FR/97")

866075-001

(Alias Part Numbers:

"9-1196743-7"

"SST-48-30/FR/97")

CM5885-000

CB5279-000

CN2234-000

E32155-000

(Alias Part Numbers:

"6-1200897-4"

"SST-30-04/CL/226")

CB5350-000

729259-001

(Alias Part Numbers:

"8-1195697-0")

CB5332-000

(Alias Part Numbers:

"SST-48-07/97/NM"

"3-1899566-0")

CB5395-000

CB5394-000

CM2027-000

(Alias Part Numbers:

Product Affected

"SST-48-07/FR/YLW/97")

CF3727-000

CB5409-000

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.