



# Product Change Notification

Current Date: 17-Feb-2020

## TE Connectivity

**Product Change Notification:** P-20-018687

**PCN Date:** 14-FEB-20

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Product migration notification

**Description of Changes**  
TE Industrial is plans to migrating per June 1st 2020 a portion of the business from the Le Mans facility to the TE Connectivity location in Bydgoszcz, Poland. As a result the part numbers below will be transferred with new production estimated to start beginning from October 2020. The part numbers below are based on the last two years sales history, a full history from September 2012 is available on request. Should you need any further information then please contact your usual TE Connectivity point of contact.

<b>Reason for Changes:</b>	
<b>Estimated Dates:</b>	
<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	01-OCT-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1580-0003B10</a>	NO			DPM1580-0003B			
<a href="#">ZPF000000000114723</a>	NO			1-1899817-8, OUT1603-0413-0			
<a href="#">ZPF000000000114726</a>	NO			DSFS24234-000A3			
<a href="#">ZPF000000000116803</a>	NO			CLN0748-0001-A0004			
<a href="#">ZPF000000000116805</a>	NO			CLN0748-0001-B0003			
<a href="#">ZPF000000000116828</a>	NO			CLN0748-0034-A0003			
<a href="#">ZPF000000000116927</a>	NO			CMB1688-0008-00000			
<a href="#">ZPF000000000116928</a>	NO			CMB1688-0008-A0001			
<a href="#">ZPF000000000116929</a>	NO			CMB1688-0009-00000			
<a href="#">ZPF000000000116930</a>	NO			CMB1688-0009-A0001			
<a href="#">ZPF000000000116976</a>	NO			CMC1590-0022-B0001			
<a href="#">ZPF000000000116978</a>	NO			CMC1590-0023-B0001			
<a href="#">ZPF000000000116983</a>	NO			CMC1592-0022-B0001			
<a href="#">ZPF000000000117752</a>	NO			CSF2544-0035-00000			
<a href="#">ZPF000000000117758</a>	NO			CSF2544-0039-A0003			
<a href="#">ZPF000000000117780</a>	NO			CSF2544-0106-A0001			
<a href="#">ZPF000000000117785</a>	NO			CSF2544-0111-A0005			
<a href="#">ZPF000000000117787</a>	NO			CSF2544-0112-A0002			
<a href="#">ZPF000000000117794</a>	NO			CSF2544-0124-00000			
<a href="#">ZPF000000000117797</a>	NO			CSF2544-0137-00000			
<a href="#">ZPF000000000117805</a>	NO			CSF2544-0143-C0001			
<a href="#">ZPF000000000117862</a>	NO			CUPFPPTHFXT72, CUP F PTH FXT72			
<a href="#">ZPF000000000117866</a>	NO			CUPMPPTHFXT72,E24276-0003, CUP M PTH FXT72			
<a href="#">ZPF000000000118806</a>	NO			DSFS1544-0015			
<a href="#">ZPF000000000118813</a>	NO			DSFS18513-0004			
<a href="#">ZPF000000000118831</a>	NO			DSFS31772-000X2			
<a href="#">ZPF000000000118846</a>	NO			DSR23609-000A3			
<a href="#">ZPF000000000118860</a>	NO			DSRS25091-0003			
<a href="#">ZPF000000000118915</a>	NO			DUP1128-0011A3			
<a href="#">ZPF000000000118928</a>	NO			DUPS1128-0009			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">ZPF000000000118937</a>	NO			EKO1756-0001-A0004			
<a href="#">ZPF000000000118940</a>	NO			EKO1756-0002-A0005			
<a href="#">ZPF000000000118947</a>	NO			EKO1756-0005-A0003			
<a href="#">ZPF000000000118951</a>	NO			EKO1791-0001-A0007			
<a href="#">ZPF000000000118968</a>	NO			EKO1791-0002-A0006			
<a href="#">ZPF000000000118969</a>	NO			EKO1791-0002-A0007			
<a href="#">ZPF000000000118991</a>	NO			EKO1791-0003-C0001			
<a href="#">ZPF000000000118999</a>	NO			EKO1791-0004-B0010			
<a href="#">ZPF000000000119916</a>	NO			SRCR26P20-15PNRMEG, SRC R 26P 20-15PN RMEG			
<a href="#">ZPF000000000119925</a>	NO			SRCR26P20-15SN, SRC R 26P 20-15SN			
<a href="#">ZPF000000000119935</a>	NO			SRCR26X18-19PN, SRC R 26X 18-19PN			
<a href="#">ZPF000000000119937</a>	NO			SRCR26X18-19PNRME, SRC R 26X 18-19PN RME			
<a href="#">ZPF000000000121694</a>	NO			CMC33EA07-07PNA01			
<a href="#">ZPF000000000134308</a>	NO			CER0648-0062-0M000			
<a href="#">ZPF000000000202653</a>	NO			CMB36PG19-4APNL090			



# Product Change Notification

Current Date: 17-Feb-2020

## TE Connectivity

**Product Change Notification:** P-20-018687

**PCN Date:** 14-FEB-20

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
Product migration notification

**Description of Changes**  
TE Industrial is plans to migrating per June 1st 2020 a portion of the business from the Le Mans facility to the TE Connectivity location in Bydgoszcz, Poland. As a result the part numbers below will be transferred with new production estimated to start beginning from October 2020. The part numbers below are based on the last two years sales history, a full history from September 2012 is available on request. Should you need any further information then please contact your usual TE Connectivity point of contact.

Reason for Changes:	
<b>Estimated Dates:</b>	
<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	01-OCT-2020
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1580-0003B10</a>	NO			DPM1580-0003B			
<a href="#">ZPF000000000114723</a>	NO		OUT1603-0413-0	1-1899817-8, OUT1603-0413-0			
<a href="#">ZPF000000000114726</a>	NO		DSFS24234-000A3	DSFS24234-000A3			
<a href="#">ZPF000000000116803</a>	NO		DEUCLN0748-0001-A0004, CLN0748-0001-A0004	CLN0748-0001-A0004			
<a href="#">ZPF000000000116805</a>	NO		CLN0748-0001-B0003	CLN0748-0001-B0003			
<a href="#">ZPF000000000116828</a>	NO		CLN0748-0034-A0003	CLN0748-0034-A0003			
<a href="#">ZPF000000000116929</a>	NO		CMB1688-0009-00000	CMB1688-0009-00000			
<a href="#">ZPF000000000116930</a>	NO		CMB1688-0009-A0001	CMB1688-0009-A0001			
<a href="#">ZPF000000000117752</a>	NO		CSF2544-0035-00000	CSF2544-0035-00000			
<a href="#">ZPF000000000117758</a>	NO		CSF2544-0039-A0003	CSF2544-0039-A0003			
<a href="#">ZPF000000000117785</a>	NO		CSF2544-0111-A0005	CSF2544-0111-A0005			
<a href="#">ZPF000000000117787</a>	NO		CSF2544-0112-A0002	CSF2544-0112-A0002			
<a href="#">ZPF000000000117794</a>	NO		CSF2544-0124-00000	CSF2544-0124-00000			
<a href="#">ZPF000000000117797</a>	NO		CSF2544-0137-00000	CSF2544-0137-00000			
<a href="#">ZPF000000000117805</a>	NO		CSF2544-0143-C0001	CSF2544-0143-C0001			
<a href="#">ZPF000000000117862</a>	NO		CUPFPPTHFXT72	CUPFPPTHFXT72, CUP F PTH FXT72			
<a href="#">ZPF000000000117866</a>	NO		CUPMPPTHFXT72	CUPMPPTHFXT72, E24276-0003, CUP M PTH FXT72			
<a href="#">ZPF000000000118806</a>	NO		DSFS1544-0015	DSFS1544-0015			
<a href="#">ZPF000000000118813</a>	NO		DSFS18513-0004	DSFS18513-0004			
<a href="#">ZPF000000000118831</a>	NO		DSFS31772-000X2	DSFS31772-000X2			
<a href="#">ZPF000000000118846</a>	NO		DEUDSR23609-000A3, DSR23609-000A3	DSR23609-000A3			
<a href="#">ZPF000000000118860</a>	NO			DSRS25091-0003			
<a href="#">ZPF000000000118915</a>	NO		DUP1128-0011A3	DUP1128-0011A3			
<a href="#">ZPF000000000118928</a>	NO			DUPS1128-0009			
<a href="#">ZPF000000000118937</a>	NO			EKO1756-0001-A0004			
<a href="#">ZPF000000000118940</a>	NO			EKO1756-0002-A0005			
<a href="#">ZPF000000000118947</a>	NO			EKO1756-0005-A0003			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">ZPF000000000118951</a>	NO			<b>EKO1791-0001-A0007</b>			
<a href="#">ZPF000000000118968</a>	NO		EKO1791-0002-A0006	<b>EKO1791-0002-A0006</b>			
<a href="#">ZPF000000000118969</a>	NO		EKO1791-0002-A0007	<b>EKO1791-0002-A0007</b>			
<a href="#">ZPF000000000118991</a>	NO			<b>EKO1791-0003-C0001</b>			
<a href="#">ZPF000000000118999</a>	NO			<b>EKO1791-0004-B0010</b>			
<a href="#">ZPF000000000119916</a>	NO		SRCR26P20-15PNRMEG	<b>SRCR26P20-15PNRMEG, SRC R 26P 20-15PN RMEG</b>			
<a href="#">ZPF000000000119925</a>	NO		SRCR26P20-15SN	<b>SRCR26P20-15SN, SRC R 26P 20-15SN</b>			
<a href="#">ZPF000000000119935</a>	NO		SRCR26X18-19PN	<b>SRCR26X18-19PN, SRC R 26X 18-19PN</b>			
<a href="#">ZPF000000000121694</a>	NO		CMC33EA07-07PNA01	<b>CMC33EA07-07PNA01</b>			
<a href="#">ZPF000000000134308</a>	NO		CER0648-0062-0M000	<b>CER0648-0062-0M000</b>			
<a href="#">ZPF000000000202653</a>	NO			<b>CMB36PG19-4APNL090</b>			