## **INFORMATION NOTE**



N° 027/20

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Early Problem Notification GTM\_AI.348 affecting DPLL operation in GTM module of dedicated TC3xx and TC2xx Microcontrollers

Infineon Technologies AG Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0 Chairman of the Supervisory Board: Dr. Wolfgang Eder Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider Registered Office: Neubiberg Commercial Register: München HRB 126492

## **INFORMATION NOTE**



## N° 027/20

Early Problem Notification GTM\_AI.348 affecting DPLL operation in GTM module of dedicated TC3xx and TC2xx Microcontrollers

►	Products affected:	Please refer to attached affected product list 1_cip02720	
•	Detailed Change Information:		
	Subject:	module of dedicated TC3xx and TC2xx Microcontrollers	
	Reason:		
	Description:	Old	New
		<ul> <li>Not applicable (no previous release)</li> </ul>	<ul> <li>Early Problem Notification GTM_AI_348_EPN_v1_0 (first release)</li> </ul>
•	Product Identification:	Not applicable (no change of produc	t)
► Impact of Change:		Assessment in Application required !	!
•	Attachments:	Affected product list: 1_cip027 GTM_AI_348_EPN_v1_0: 4_cip027	
	Intended start of	Notapplicable	
•	delivery:	Not applicable	

If you have any questions, please do not hesitate to contact your local Sales office.