



TE Connectivity

Product Change Notification: P-20-018882

PCN Date: 06-APR-20

Location: WORLDWIDE

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Notification of packaging changes for -STK tubing products.

Description of Changes
This is a notification informing TE Connectivity customers that the packaging boxes used for the tubing -STK products will be changing.
Other attachments:
[Stick parts for Box changes Q232](#)
[New Stick Boxes 2020](#)
[PCN - Changes to -STK boxes](#)

Reason for Changes:
Product improvement. We are moving to a more robust design that will give better protection to the tubing products during transportation. The boxes are moving from a square profile to a rectangular one with different cardboard and latching method. We will be transitioning boxes as existing packaging is consumed so not all product will change at the same time.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	08-APR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments (Changed Parts Only):
	31-OCT-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3000812004	NO			"1192273-5", "ATUM-6/2-X-STK"			
4951522003	NO			"6-1193702-6", "ATUM-32/8-0-STK"			
5052842031	NO			"3-1193821-7", "RNF-100-3/64-0-STK"			
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
5053022021	NO			"7-1193836-9", "RNF-100-1/8-6-STK"			
5053032054	NO			"4-1193837-2", "RNF-100-1/8-9-STK"			
5053082028	NO			"8-1193843-3", "RNF-100-3/16-9-STK"			
5053142077	NO			"2-1193853-0", "RNF-100-3/8-0-STK"			
5053242048	NO			"1-1193869-6", "RNF-100-3/4-0-STK"			
5053392024	NO			"7-1193885-5", "RNF-100-2-0-STK"			
5053412010	NO			"6-1193886-8", "RNF-100-2-4-STK"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			
5069822045	NO			"7-1193948-4", "CGPT-3.2/1.6-0-STK"			
5070042035	NO			"9-1193960-1", "RNF-100-1/8-X-STK"			
5070052031	NO			"1-1193962-0", "RNF-100-3/16-X-STK"			
5070072039	NO			"1-1193964-4", "RNF-100-3/8-X-STK"			
5070082037	NO			"2-1193965-0", "RNF-100-1/2-X-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
5677552005	NO			"2-1194493-0", "RNF-3000-1.5/0.5-0-STK"			
5677632005	NO			"2-1194499-2", "RNF-3000-3/1-2-STK"			
5677682004	NO			"6-1194500-8", "RNF-3000-39/13-2-STK"			
5677752004	NO			"2-1194503-5", "RNF-3000-39/13-4-STK"			
5873232004	NO			"2-1194648-9", "CGAT-3/1-0-STK", "42CGAT31-M"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB10892001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB12762001	NO						
NB13052001	NO						
NB13542001	NO						
NB13892001	NO						
NB14832001	NO						
NB14902001	NO						
NB14932001	NO						
NB14942001	NO						
NB16352001	NO						
NB16502001	NO						
NB18302001	NO						
NB18932001	NO						
NB19112001	NO						
NB19162001	NO						
NB25842001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB14832001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10802001	NO						
NB11382001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509092132	NO			"5-1194348-8", "ATUM-6/2-0-MS-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5500702004	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
NB13542001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
NB10132001	NO						
NB11382001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB13892001	NO						
NB14932001	NO						
NB18302001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052842031	NO			"3-1193821-7", "RNF-100-3/64-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
5053142077	NO			"2-1193853-0", "RNF-100-3/8-0-STK"			
5067452035	NO			"9-1193932-6", "ATUM-19/6-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509102149	NO			"1194350-8", "ATUM-12/4-0-MS-STK"			
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
NB10892001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			

Part Number(s)

being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10132001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB14832001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4951522003	NO		ATUM32/8BLK4'LENGTHS, ATUM-32/8-0-STK, 80808, ATUM-32/8-0-STK-IN, 929903, 603100, 47484G, 002921	"6-1193702-6", "ATUM-32/8-0-STK"			
5500702004	NO		613250, TAT-125-3/8-0-STK-IN, TAT-125-3/8-0-STK, 932430, 643247, TAT-125-3/8-0-4FT, 93885, 06250, 93883, TAT125-3/8-0-4FT	"7-1194335-4", "TAT-125-3/8-0-STK"			
5509092033	NO		ATUM-6/2-0-STK-IN, ATUM-6/2-0-STK	"5-1194348-1", "ATUM-6/2-0-STK"			
5509112121	NO			"7-1194351-0", "ATUM-24/8-0-MS-STK"			
5509122113	NO			"9-1194352-5", "ATUM-40/13-0-MS-STK"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB11802001	NO						
NB12042001	NO						
NB12762001	NO						
NB13052001	NO						
NB13892001	NO						
NB14902001	NO						
NB14932001	NO						
NB14942001	NO						
NB16352001	NO						
NB16502001	NO						
NB18302001	NO						
NB19112001	NO						
NB19162001	NO						
NB25842001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3000812004	NO			"1192273-5", "ATUM-6/2-X-STK"			
4951522003	NO			"6-1193702-6", "ATUM-32/8-0-STK"			
5052842031	NO			"3-1193821-7", "RNF-100-3/64-0-STK"			
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
5053032054	NO			"4-1193837-2", "RNF-100-1/8-9-STK"			
5053082028	NO			"8-1193843-3", "RNF-100-3/16-9-STK"			
5053142077	NO			"2-1193853-0", "RNF-100-3/8-0-STK"			
5053242048	NO			"1-1193869-6", "RNF-100-3/4-0-STK"			
5053392024	NO			"7-1193885-5", "RNF-100-2-0-STK"			
5053412010	NO			"6-1193886-8", "RNF-100-2-4-STK"			
5070042035	NO			"9-1193960-1", "RNF-100-1/8-X-STK"			
5070052031	NO			"1-1193962-0", "RNF-100-3/16-X-STK"			
5070072039	NO			"1-1193964-4", "RNF-100-3/8-X-STK"			
5070082037	NO			"2-1193965-0", "RNF-100-1/2-X-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			
5677552005	NO			"2-1194493-0", "RNF-3000-1.5/0.5-0-STK"			
5677632005	NO			"2-1194499-2", "RNF-3000-3/1-2-STK"			
5677682004	NO			"6-1194500-8", "RNF-3000-39/13-2-STK"			
5677752004	NO			"2-1194503-5", "RNF-3000-39/13-4-STK"			
5873232004	NO			"2-1194648-9", "CGAT-3/1-0-STK", "42CGAT31-M"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB11802001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3000812004	NO			"1192273-5", "ATUM-6/2-X-STK"			
4951522003	NO			"6-1193702-6", "ATUM-32/8-0-STK"			
5052842031	NO			"3-1193821-7", "RNF-100-3/64-0-STK"			
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
5053032054	NO			"4-1193837-2", "RNF-100-1/8-9-STK"			
5053082028	NO			"8-1193843-3", "RNF-100-3/16-9-STK"			
5053142077	NO			"2-1193853-0", "RNF-100-3/8-0-STK"			
5053242048	NO			"1-1193869-6", "RNF-100-3/4-0-STK"			
5053392024	NO			"7-1193885-5", "RNF-100-2-0-STK"			
5053412010	NO			"6-1193886-8", "RNF-100-2-4-STK"			
5070042035	NO			"9-1193960-1", "RNF-100-1/8-X-STK"			
5070052031	NO			"1-1193962-0", "RNF-100-3/16-X-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5070072039	NO			"1-1193964-4", "RNF-100-3/8-X-STK"			
5070082037	NO			"2-1193965-0", "RNF-100-1/2-X-STK"			
5108762003	NO			"4-1194015-2", "RAYRIM-NR6-0-STK"			
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			
5677552005	NO			"2-1194493-0", "RNF-3000-1.5/0.5-0-STK"			
5677632005	NO			"2-1194499-2", "RNF-3000-3/1-2-STK"			
5677682004	NO			"6-1194500-8", "RNF-3000-39/13-2-STK"			
5677752004	NO			"2-1194503-5", "RNF-3000-39/13-4-STK"			
5873232004	NO			"2-1194648-9", "CGAT-3/1-0-STK", "42CGAT31-M"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB18932001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV25362001	NO			"RW-175-E-1/16-X-STK", "5-1899810-3"			
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			
NB11382001	NO						

Customer:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5509092033	NO			"5-1194348-1", "ATUM-6/2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10802001	NO						
NB11382001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			

Part Number(s)

being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB10132001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4951522003	NO		ATUM32/8BLK4'LENGTHS, ATUM-32/8-0-STK, 80808, ATUM-32/8-0-STK-IN, 929903, 603100, 47484G, 002921	"6-1193702-6", "ATUM-32/8-0-STK"			
5500702004	NO		613250, TAT-125-3/8-0-STK-IN, TAT-125-3/8-0-STK, 932430, 643247, TAT-125-3/8-0-4FT, 93885, 06250, 93883, TAT125-3/8-0-4FT	"7-1194335-4", "TAT-125-3/8-0-STK"			
5509092033	NO		ATUM-6/2-0-STK-IN, ATUM-6/2-0-STK	"5-1194348-1", "ATUM-6/2-0-STK"			
NB09952001	NO			"ATUM--19/6-0-STK"			
NB10132001	NO						
NB10802001	NO						
NB11242001	NO			"ATUM--40/13-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB11382001	NO						
NB11622001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11802001	NO						
NB12042001	NO						
NB12762001	NO						
NB13052001	NO						
NB13892001	NO						
NB14902001	NO						
NB14942001	NO						
NB16352001	NO						
NB16502001	NO						
NB19112001	NO						
NB19162001	NO						
NB25842001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB11652001	NO			"ATUM--6/2-0-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5053022021	NO			"7-1193836-9", "RNF-100-1/8-6-STK"			
5069822045	NO			"7-1193948-4", "CGPT-3.2/1.6-0-STK"			
5070052031	NO			"1-1193962-0", "RNF-100-3/16-X-STK"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5070072039	NO			"1-1193964-4", "RNF-100-3/8-X-STK"			
5677552005	NO			"2-1194493-0", "RNF-3000-1.5/0.5-0-STK"			
9998552005	NO			"8-1197729-0", "DWTC-16/4-X-STK"			
NB10802001	NO						
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5052992082	NO			"1-1193833-3", "RNF-100-1/8-0-STK"			
CV25342001	NO			"RW-175-E-1/4-X-STK", "5-1899810-4"			