


## L1380 SUPPORT



Moulded supports may either be mounted on the same fixing centres as the connector, or stood off to accommodate wider boards



PANEL CUT-OUTS viewed from P.C. side Dimension 'x' to be fixing centres of any P.C. connector Location dowel holes to be within 0.05mm dia of true position



BLP reserve the right to change without prior notice the information contained within this leaflet