

1 Products affected

Product hierarchy no. *			hier	archy no. *	Part no.	SBU	Type / Description	Customer part no.
S	BU	PG	PUG	Туре				
_	າວ	OOE	5 016	0000001101	See list	Power entry modules without line	00/12 2 CD	
·	,,	003			below	filter	0043-2 SF	


*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)

ist of part numbers affected									
0040.5000.2									

2 Type of change

Change of approval and rating markings on the moulding body.

3 Detailed description of change



Approvals CSA and UR replaced to cURus. 6A 250V~ removed.

4 Reason of change

Standards update according to the new UL/CSA 60320-1

5 Release date

The change will be rolled out starting ww 12/2020 (Date code 2012 or higher on packaging label) and lasts approx. 6 months depending on the variant. This change has no effect on the validity of the approval certificates.

Product CI	Product Change Notification						8843-2 SP Change of inscription			
owner	creation date	release date	released by	change order no	rev	page	D40 040 406			
sariogar	09.01.2020	18.03.2020	sariogar	2018961	Α	1 of 2	D10-042-126			



6 Impact of change and recommended action

Form Yes Change of approval marks and rating.

Fit No Function No Manufacturing No Label No Packaging No -

7 Reference Documents / Attachments

Kind of document	Remarks			
8843-2 SP Data sheet				

Product Change Notification						8843-2 SP Change of inscription			
owner	creation date	release date	released by	change order no	rev	page	D40 040 406		
sariogar	09.01.2020	18.03.2020	sariogar	2018961	Α	2 of 2	D10-042-126		