



# Product Change Notification

Current Date: 30-Jun-2020

## TE Connectivity

Product Change Notification: E-20-008995

PCN Date: 29-JUN-20

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Size 20 Socket Contact, Crimp

**Description of Changes**

Removing material option that no longer has an active TE material specification and is not in use. Updating the crimp barrel hardness after annealing to match supplier process.

**Reason for Changes:**

Product Improvement. Updating the print to match the supplier's process

**Estimated Dates:**

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

15-JUL-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-205089-1</a>	NO						
<a href="#">205089-1</a>	NO			"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
<a href="#">205089-4</a>	NO						

Customer: TTI, Inc. ( 1305175 )

Location: Maisach-gernlinden

Agreement Number: TTI001

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-205089-1</a>	NO		TYC1-205089-1				
<a href="#">205089-1</a>	NO		TYC205089-1	"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			

Customer: TTI Inc ( 1281288 )

Location: Fort Worth

Agreement Number: TTI002

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205089-1</a>	NO			"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
<a href="#">205089-4</a>	NO						

Customer: TTI Inc ( 168830 )

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205089-1</a>	NO			"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			
<a href="#">205089-4</a>	NO						

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-gerlninden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205089-1</a>	NO		TYC205089-1	"033-0011-00", "CC5847-000", "HD 20 PIN CONTACT", "4-16211-7508"			

Customer: TTI Electronics Asia Pte Ltd. ( 2771300 )

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205089-4</a>	NO						

Customer: TTI Electronics Asia Pte Ltd. ( 1407161 )

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">205089-4</a>	NO						